

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 13; & 18, T29-8

| Alias | Description |
|-------|-------------|
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 16 Page(s) 6573)

Set ¼ sec. post, from which
A Chinquapin 18" dia., bears N.27°W., 44 lks. dist.
A Fir 24" dia., bears S.30°E., 15 lks. dist.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #'s 350 & 606, surveyed Aug/Oct. 1966 - (DCSO records Vol. 34 Page(s) 14001)

The ¼ sec. cor., determined at record bearing and distance from the remains of the original bearing trees:

A burned and rotted shell of a Fir, 48" dia., bears S.30°E., 15 lks. dist., with scribe mark S visible on bark blaze.

A down and rotted Chinquapin 18" dia., bears N.27°W., 44 lks. dist., no marks visible.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

T 29 S
R 9 W R 8 W
¼
S 13 | S 18
1966

from which new bearing trees:

A Fir 24" dia., bears N.30°E., 14½ lks. mkd. ¼ S18 BT.

A W.Fir 14" dia., bears N.68°W., 23 lks. mkd. ¼ S13 BT.

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #2008, surveyed June/July 2002- (DCSO rec. Vol. 54 Page(s) 21051)

Beginning at the ¼ sec. cor. of secs. 13 & 18, on the E. bdy. of the Tp., monumented with an iron post, 2½" dia., firmly set, projecting 10" above ground, w/brass cap (properly) mkd. from which the remains of the bearing trees mkd. by Jelley

A fir stump, 31" dia. bears N.30°E. 9.6 ft. w/healed blaze

A fir, 26" dia., bears N.68°W., 15.2 ft. with healed blaze and a new bearing tree

A cedar, 22" dia., bears N.2¾°E., 9.9 ft., mkd. ¼ S18 BT.

Cor. is located on NW. slope, at E. end of four-strand barbed wire fence which extends West.

Each new BT has a 2½"x¼" magnetic nail (MAG-NAIL) driven at the base on the right side-center, unless otherwise described in the corner description.