

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Fred Mensch, US Deputy Surveyor, under contract No. 797, dated April 19, 1910 - (DCSO records Vol. 25 Page 10569 & Vol. 26 Page 10967)

Set a conglomerate stone 15x10x8", 10" in the ground for ¼ sec. cor. mkd. ¼ on N face, from which
A hemlock, 8" dia., bears N.1°E., 11 lks., mkd: ¼ S31 BT.
A hemlock, 12" dia., bears S.40°E., 12 lks., mkd: ¼ S6 BT.

GLO survey by Fred Mensch, Cadastral Engineer, under special instructions Dated June 7, 1922 - (DCSO records Vol. 26 Page(s) 10986-7)

The ¼ sec. cor. established for secs. 6 & 31, which is a conglomerate stone, 10x8x5" above ground, firmly set, marked & witnessed as described by the surveyor general. Hereafter this cor. will refer to sec. 31 only. I mark the cor. stone ¼ S 31 on N face, from which
A hemlock, 8" dia., bears N.1°E., 11 lks., mkd: ¼ S31 BT, old BT.
A cedar, 10" dia., bears N.78°W., 38 lks., mkd: ¼ S31 BT. I obliterate the marks on the old BT in Sec. 6.

Dennis Gaylord, USFS & DCSO Deputy - Walter Barton - April 21, 1977 - C.S. File 59/31-28

Found - Broken pile of stone at corner location. No identifiable marks. (No other stones in area).
A 10" Hemlock, is down & decayed. Stump hole bears N.1°E., 7.26 ft. open partly healed blaze & find scribing "1/4 S31 BT".
A 14" Hemlock id down & decayed, stump hole bears S.40°E., 7.92 ft. Open blaze & find fragments of scribing & reverse.
A stump hole is N.78°W., 25.08 ft., location of orig. NW BT.

Set - 2½" brass cap on 1½" I.P. stamped County Surveyors Office T29S R1E ¼ S31 1977. (set by reference to stump holes of orig. BTs, which is in pile of broken stones).

New BTs- A 9" Ponderosa Pine bears N.10°30'W., 27.3 ft. scribed "¼ S31 CS BT" on a double blaze.
A 6" Ponderosa Pine bears N.67°E., 7.7 ft. scribed "¼ S31 CS BT" on a double blaze.

Note - Corner lies 100 ft. West of F.S. Road No. 298J in a burned of clearcut unit.

