

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19; 13 & 24, T30-2

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6651)

Set post corner secs. 18, 19, 13 and 24, from which

- A Fir 8" dia., bears S.14°E., 12 lks.
- A Fir 12" dia., bears N.50°E., 31 lks.
- A Fir 9" dia., bears N.75°W., 13 lks.
- A Laurel 10" dia., bears S.68°W., 22 lks.

Ben B. Irving, Deputy Co. Surveyor - Wit: N.E. Richardson; Loren Weber - Aug. 2, 1940 - C.S. File 16/55

Location identified from original BTs:

- A 24" Fir N.56¼°E., 31 lks., partially visible.
- A 12" Fir S.79½°W., chopped out BT which is very plain.

Set a stone 6"x8"x18" for corner, from which

- Fir 20" dia. bears S.53 3/4°E., 14.8 ft. mkd. T30S R1W S19 CS BT.
- Fir 18" dia. bears S.79½°W., 19.4 ft. mkd. T30S R2W S24 CS BT. (Orig. BT)
- Fir 24" dia. bears N.56¼°E., 20.0 ft. mkd. T30S R1W S18 CS BT.
- Fir 24" dia. bears N.62½°W., 48.2 ft. mkd. T30S R2W S13 CS BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & W. Penley, crew - Jan/Feb. 1968 - C.S. File 54/59-115

Found - Stone at section corner, 6 x 8 x 18 ins.

- Orig. 8" D.Fir, now stob, S.14°E., 7.9 ft., old axe work "B" visible.
- Orig. 9" D.Fir now rotten stump and hole, N.75°W., 8.6 ft.
- 20" D.Fir S.53½°E., 14.8 ft., bark scribe visible "T30S R1W S19 CS BT".
- 18" D.Fir S.79½°W., 19.4 ft., bark scribe visible.
- 24" D.Fir N.56°E., 20.0 ft., bark scribe visible, possible orig. BT.
- 24" D.Fir N.62½°W., 48.2 ft., bark scribe visible.

Set Brass cap at cor. mkd: County Surveyors Office

R	T 30 S	R
2	S 13 S 18	1
W	S 24 S 19	W
	1968	

Bearing trees all in good condition, OK and tagged.

(Cont. Next Page)

TOWNSHIP 30 RANGE 01 POINT IDENTIFIER # 100400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19; 13 & 24, T30-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Glenn S. Baughman, LS #536 - For: U.S. Forest Service - May 23, 1978 - C.S. File 58/153-6

Found - A 1" I.P. with 2½" brass cap 14" above ground.
8" D.Fir stob, bears S.9°E., 7.9 ft. (Rec. S.14°E.),
scribe visible, open blaze.
20" D.Fir bears S.53½°E., 14.8 ft., bark scribes
visible.
24" D.Fir bears N.56°E., 20.0 ft., barks scribes
visible.
18" D.Fir stump bears S.79°W., 19.4 ft., bark
scribes visible.
24" D.Fir bears N.62°W., 48.2 ft., bark scribes
visible.
6" x 8" x 5" high stone buried alongside 1" I.P.
New BT - 10" Madrone bears S.74°W., 18.0 ft. scribed "T30S
R2W S24 BT" on a double blazed face.
Corner lies at the foot of a very steep North slope and 50
ft. South of dirt road built recently. Corner has been run
over by cat during logging and iron pipe is badly bent.

Fd. OK, Dec. 1994 - M 121-45