

TOWNSHIP 30 RANGE 01 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 32 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor under contract 73 dated June 8, 1857 - (DCSO Records Vol 16 Pg 6660

Set ¼ sec. post, from which
A cedar, 15" dia., bears S.5°W. 12 lks.
A laurel, 10" dia., bears S.30°E. 16 lks.

John Markham, Jr. - Jan. 1961 - C.S. File 51/121-4

Found - 30" Cedar S.5°W., 7.9 ft. OBT, fd. scribe.
At corner point set 2"x36" truck axle with flange up, from which:
6" cedar S.51°E., 22.6 ft. ¼ S33 BT.
16" La. East 38.0 ft. mkd: ¼ S33 BT.
5" W.Fir N.55°E., 39.0 ft. ¼ S33 BT.
50" Fir N.8°W., 47.4 ft. ¼ S32 BT.

Fd. Ok 2/6/1968, JMP, C.S. File 54/59-60

William Ruppert - For: USFS - Witness: D. Stringer - Sept. 1, 1977 - C.S. file 58/156-1

Found - 1½"x40" steel shaft with 3¼" flange on top. 1961
29" Cedar windfall approx. 8 ft. south, no scribe visible
50" D.Fir stump bears N.10°W., 46.5 ft. Good scar.
12" Fir, bars N.53°45'E., 38.5 ft. Good scar.
24" Madrone bears N.85°50'E., 37.6 ft. Scars
8" Cedar bears S.53°30'E., 22.6 ft. Scribe visible.
Set - 2"x 30" Gal. Pipe with 2½" brass cap marked T30S R1W
¼ S32 S33 PLS 866 1977.
New BT - 10" W.Fir bears N.47°30'W., 74.4 ft. scribed ¼ S 32
BT. Tagged 3/4" washer RLS 866.
Replace steel shaft alongside brass cap. Set 6 ft. steel post
4 ft. north of cap. Attached USFS signs 54-2 and 54-4.

Tony Hostetter - For: Seneca Jones Timber Co. Co. - April 2010 - M160-57

Found - 1977 brass cap & accessories as described by Ruppert
(C.S. 58/156)
New BTs- 12" Fir scribed "S33 ¼ BT" bears N.28°23'E., 11.8
ft. to spike.
14" Fir scribed "S32 ¼ BT" bears S.86°46'W., 26.0
ft. to spike.