

TOWNSHIP 30 RANGE 01 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Cor. Secs 8, 9, 16 & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, US Deputy Surveyor, contract 73 dated June 8, 1857 - (DCSO Records Vol. 16 Pg 6663)

Set post corner secs. 8, 9, 16, & 17 from which
A pine, 18" dia., bears S.85°W., 14 lks.
A pine, 12" dia., bears S.60°E., 8 lks.
An oak, 24" dia., bears N.25°W., 60 lks.
An oak, 10" dia., bears N.45°E., 134 lks.

GL0 corrective survey by Fred Mensch, Dep. Surveyor, Contract #757 dated Sept. 14, 1904 - (DCSO records Vol. 16 Pgs 6692-3)

The old corner which was a post has disappeared, and three of the BTs are dead though still standing. I obliterate the old marks & re-establish the corner in its orig. position as follows:
Set a basalt stone 15x10x8", 10" in the ground for cor. of secs. 8, 9, 16, & 17 mkd with 4 notches on S & E edges, from which
A B.Oak, 12" dia., bears N.45°E., 131 lks., mkd: T30S R1W S9 BT.
A B.Oak, 10" dia., bears S.60°E., 68 lks., mkd: T30S R1W S16 BT.
A Y.Pine, 24" dia., bears S.82°W., 14 lks., mkd: T30S R1W S17 BT.
A Y.Pine, 24" dia., bears N.54°W., 155 lks., mkd: T30S R1W S8 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - June 1968 - C.S. File 54/59-82

Found - Broken Stone at Corner with 4 grooves.
24" Pine, now snag, S.82°W. 9.2 ft., burnt face, faint "4" visible.
24", now 31" Pine, N.54°W. 102.3 ft., shows good scar.
Remains of Oak about S.60°E. 44.9 ft.
Set - Brass Cap at Cor. mkd: County Surveyors T30 R1W
Office S 8 | S 9
1968 S 17 | S 16
New BTs- 12" D.Fir N.40½°W. 29.2 ft. mkd: T30S R1W S8 CS BT.
9" D.Fir N.35°E. 19.5 ft. mkd. T30S R1W S9 CS BT.
8" D.Fir S.38°E. 13.4 ft. mkd. T30S R1W S16 CS BT.
13" D.Fir S.14°W. 29.2 ft. mkd. T30S R1W S17 CS BT.

continued next page
1

PRIMARY CORNER DESCRIPTION Cor Secs 8, 9, 16 & 17

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Douglas Co. Surveyors Office - Crew: Stephen Flauser & Jeff Lorsung- 4/17/2019 (Filed 11/18/2021) - C.S. File 67/50-26

-
- Found - 1968 DCSO 2½" dia., brass cap on a 1" I.D. iron pipe (properly marked) projecting 8" above a rough 2 ft dia., mound of stone.
Evidence of one OBT from 1857 a tree (pine or fir) rotted to ground Oak; bears S.82°W., 9.2 ft. (as per Mensch 1904)
Remains of rotted to ground Oak; bears S.60°E., 44.9 (as per rec) 1904
A 30" dia., 1 ft tall rotted Pine stump with blaze scars no longer vis; bears N.54°W., 102.3 ft. (as per rec) 1904
A 15" dia., D.Fir with a FHDB; bears N.35°E., 19.5 ft. (as per rec) 1968
A 14" dia., D.Fir with a FHDB; bears S.38°E., 12.9 ft. (Rec S.38°E., 13.4) 1968
A 19" dia., 14 ft. tall dead D.Fir snag with a FHDB; bears S.11°W., 29.2 ft (rec S.14°W. 29.2 ft) Distance measured to 4" MAG NAIL set in left side-cntr near base of BT. 1968
A 20" dia., D.Fir with a FHDB; bears N.40½°W., 29.2 ft. (as per rec) 1968
- New - Two possible USFS BTs (no record) these trees have shield shaped USFS location tags and show some bark scarring (from scrbg?)
An 8" dia., Madrone bears N.23°E., 2.5 ft.
A 14" dia., Madrone bears N.88°E., 4.0 ft.
- Note - Monument is 95 ft. south from forest Rd. Area SE quad is old reprod P.Pine, rest of forest is old second growth.