

TOWNSHIP 30 RANGE 01 POINT IDENTIFIER # 337600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 4 only, South

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO corrective survey by Fred Mensch, Dep. Surveyor, Contract #757 dated Sept. 14, 1904 - (DCSO records Vol. 16 Pg 6691D)

-----  
Set an ironstone 13x8x5" 9" in the ground for ¼ sec. cor. marked ¼ on N face, from which

A cedar, 14" dia., bears N.56°W., 48 lks., mkd: ¼ S4 BT.

A cedar, 10" dia., bears S.43°W., 7 lks., mkd: ¼ S9 BT.

-----  
Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - June 1968 - C.S. File 54/59-125

-----  
Found - Stone at ¼ corner mkd: "¼"

Orig. 14" now 22" cedar N.56°W., 31.7 ft., shows good scars.

10" now 17" cedar S.43°W., 4.6 ft. shows good scar.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T30S R1W

OFFICE ¼ S 4  
1968

New BT - 8" Maple N.38°W., 14.3 ft. mkd: "¼ S4 CS BT"

Bearing trees OK & tagged - I do not destroy SW BT for control purposes.