

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36 only (South)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6649)

- A Fir 12" dia., corner secs. 35, 36, 1 and 2, from which
 - A Fir 12" dia., bears S.80°W., 32 lks.
 - A Fir 10" dia., bears N.62°E., 9 lks.
 - A Fir 12" dia., bears S.40°E., 14 lks.
 - A Fir 10" dia., bears N.2°W., 236 lks.

GLO resurvey by Fred Mensch, U.S. Deputy Surveyor - under Special Instructions, dated June 7, 1922 - (DCSO records Vol. 16 Page(s) 6713-14)

The old cor. of secs. 1, 2, 35 and 36, which is a Fir, 12" dia., with marks grown over; from which

- A Fir 12" dia., bears S.40°E., 14 lks. dist. mkd. T31S R1W S1 BT. (old BT)
- A Fir 12" dia., bears S.80°W., 32 lks. dist. mkd. T31S R1W S2 BT. (Old BT)

The BT in sec. 36 is dead and fallen and the old BT in sec. 35 is rejected as appropriate witness, on account of intervening younger growth of trees and better witness now available; the marks on this old tree are deeply overgrown and not disturbed. I now change this cor. to refer to secs. 35 and 36 only, and obliterate the marks on the BTs referring to secs. 1 and 2.

Re-mark the Fir tree, T30S S36 on NE.; and R1W S35 on NW. side; from which

- A Fir 30" dia., bears N.58°E., 27 lks. dist. mkd. T30S R1W S36 BT. (New BT)
- A Fir 12" dia., bears N.29°W., 39 lks. dist. mkd. T30S R1W S35 BT. (New BT)