

TOWNSHIP 30 RANGE 01 POINT IDENTIFIER # 668600

PRIMARY CORNER DESCRIPTION NW Cor. Govt Lot #1, Sec. 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6653)

-
- A Fir 12" dia., corner secs. 6, 7, 1 and 12, from which
 - A Fir 6" dia., bears N.45°E., 4 lks.
 - A Fir 30" dia., bears S.54°E., 26 lks.
 - A Fir 9" dia., bears N.45°W., 27 lks.
 - A Hemlock 5" dia., bears S.85°W., 27 lks.

GLO survey by Homer D. Angell, Deputy Surveyor, under Contract #746, dated May 5, 1902 - (DCSO records Vol. 16 Page(s) 6685)

From the cor. for 1 & 12 only, the old corner of secs. 1, 6, 7 and 12 bears N.76°34'W., 30.03 chs. dist., which is a Fir marked and witnessed as described by the surveyor general. I destroy all marks on the old corner referring to T30S R1E.

Survey by William Ruppert LS #866 - For: U.S. Forest Service Jan. 1978 - M 65-80

(Ruppert labels corner as "AP 1 for secs. 1 & 12)
Set Brass cap marked "T30S R1W AP 1 S1 S12 RLS 866 1978", from which

- Found stump bears S.52°E., 17.2 ft. scribed "BT"
- New BT, 12" W.Fir N.31°03'E., 24.6 ft.
- New BT, 6" W.Fir S.56°11'E., 10.0 ft.