

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 31 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #766, dated May. 10, 1906 - (DCSO records Vol. 18 Page(s) 7668 3/4)

Set a granite stone 15x12x6 ins., 10" in the ground, for ¼ sec. cor., marked ¼ on N. face, from which
A Fir 6" dia., bears N.41½°E., 15 lks. mkd. ¼ S31 BT.
A Fir 15" dia., bears N.18°W., 12 lks. mkd. ¼ S31 BT.

Douglas Co. Surveyors Office - Gregory E. Quibell; Terrie Plouff; Teresa Buley, crew - Oct. 22, 1981 - C.S. 61/29-16

Found - Orig. 15"x12"x6", now 14"x11"x6" stone with a ¼ marked on N. face, buried with top flush to ground.
Orig. 15" now 22" Fir snag, 20 ft. high with good scar, bears N.12°W., 7.9 ft. (Rec. N.18°W.)
Possible orig. 6" Fir, down and rotted, at approx. original position. (unable to define root hole)
At the exact location of the orig. stone, I SET a brass cap marked: "Douglas Co. Surveyor T30S 1/4 S31 R2W 1981".
Original stone buried along N. edge of cap.
New BTs- 30" Fir scribed "S ¼ 31 CS BT" in double blaze, bears N.87½°E., 35.4 ft.
10" Fir scribed "S ¼ 6 C SBT" in double blaze, bears S.69°E., 42.8 ft.
8" Madrone scribed "S ¼ 6 CS BT" in double blaze, bears S.14°W., 21.0 ft.
42" Madrone with PK nail in base, scribed "S ¼ 6 CS BT" in double blaze, bears S.67°W., 2.9 ft. to nail.
This corner is along the southerly side of a future clear-cut

Ron Quimby - For: Roseburg Resources Co - Dec. 2014 - M166-27

Found - Brass cap per 1981 DCSO renewal
25"x3' Fir stump N.87°E., 35.4' partially visible scribe.
10" Fir stump up-rooted and rotten.
8" Madrone S.14°W., 21.0' healed face
44" Madrone S.67°W., 2.9' (To PK nail) healed face