

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29 & 30 only (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Pgs 6769-70)

-
- A Fir 18" dia., cor. secs. 19, 20, 29 and 30, from which
 - A Maple 15" dia., bears S.6°W., 56 lks.
 - A Fir 6" dia., bears S.75°E., 42 lks.
 - A Fir 50" dia., bears N.15°W, 20 lks.
 - A Fir 15" dia., bears N.2°E., 82 lks.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6801 and 6864)

(Page 6801) The cor. of secs. 19, 20, 29 and 30 almost obliterated. The Cor. tree and NW. and NE. BTs are burned and decayed. The other BTs are deeply overgrown.

(Page 6864) I re-establish the old cor. in its original position as the cor. of secs. 29 and 30 only, as follows:
Set a granite stone 14x10x7 ins., 9½" in the ground, for cor. marked with 2 notches on S & 5 notches on E. edge, from which

- A Fir 16" dia., bears S.58½°E., 34 lks. dist. mkd. T30S R2W S29 BT.
- A Fir 10" dia., bears S.57½°W., 34 lks. dist. mkd. T30S R2W S30 BT.

Douglas Co. Surveyors Office - John M Powell & crew - 11/4/1968 - C.S. File 54/73-23A

Reported as not fd
Found basalt stone 5 grooves on one side not firmly in place. Both corners (S Corner Secs. 19 & 20) lie in old unit trees completely gone from cat work. Not enough evidence to renew.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - June 29, 1970 - C.S. File 54/73-69

Found - Corner stone, approx. size, firmly in ground, 38.3 ft. West of quartz stone for cor. secs. 19 & 20.
No bearing trees found.

This and another stone I found a year ago. This year, Roseburg Lumber chained to them from the N. and E. Everything points to these stones as the corners.
Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 2 W
S 19
S 30 S 29
1970

continued next page

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 179300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29 & 30 only (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs- 10" Yew S.35°W., 20.8 ft. mkd. T30S R2W S30 CS BT.
14" Hemlock South, 10.8 ft. mkd. T30S R2W S29 CS BT.

Fd. OK, Dec. 1986/Feb. 1986 by H. Johnstone - M 11-21

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2818, surveyed Nov. 2015 - (DCSO records Vol. 58 Page 23488 & Plat T30-2 2017-1)

The cor of secs 29 & 30 only, on the S bdy of sec 19, perpetuated by the Douglas Co Surveyor's Office in 1970, monumented with an iron post, 1¼" dia., firmly set, projecting 12" above ground (alongside of which is the original granite stone, 14x10", firmly set, projecting 3" above ground, no marks visible), with brass cap (properly) mkd.

from which the BTs mkd. by the Douglas Co Surveyor's Office
A hemlock, 20" dia., bears S.2°E., 10.2 ft., with a healed blaze.

A yew, 10" dia., bears S.33¼°W., 20.0 ft., with illegible scribe marks visible on a partially healed blaze.