

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6867)

Set a granite stone 16x12x8 ins., 11" in the ground, for ¼ sec. cor. marked ¼ on W. face, from which,
A Fir 16" dia., bears S.7°E., 28 lks. dist. mkd. ¼ S32 BT.
A Fir 36" dia., bears N.49°W., 53 lks. dist. mkd. ¼ S31 BT

Bruce Shaner, L.S.. #430 - For: Roseburg Forest Products - Clem Berlier; David Snyder, crew - June 1995 - M 119-64 - C.S. File 63/161-36-B

Found - Broken, decomposed granite stone from which:
24" (rec. 16") D.Fir, O.B.T., now stump, badly rotted, with scribes "¼ S" visible, bears S.7°E., 18.5'.
36" D.Fir, O.B.T., now badly rotted root collar & rot only, bears N.48°W., 35.0'.

I set a 1"x30" I.P. with a 2½" brass cap, mkd:
T30S R2W W.M.

¼
S 31 S 32
RLS 430 1995

New BTs- 8" D.Fir BT, I scribed "¼ S31 BT" bears S.38°W., 22.6 feet.
8" D.Fir BT, I scribed "¼ S31 BT" bears N.52°W., 8.8 feet.
8" D.Fir BT, I scribed "¼ S32 BT" bears S.88°E., 14.2 feet.
12" D.Fir BT, I scribed "¼ S32 BT" bears N.34°E., 37.0 feet.
6' steel fence post bears North, 1.0 foot.