

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29 and 30 only (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6769)

Set post cor. secs. 29, 30, 31 and 32, from which
A Live Oak 6" dia., bears S.62°W., 26 lks.
A Laurel 6" dia., bears N.40°W., 26 lks.
A Laurel 9" dia., bears S.20°E., 43 lks.
A Fir 30" dia., bears N.88°E.

GL0 survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6866)

The old cor. of secs. 29, 30, 31 and 32 is nearly obliterated, the SW. BT being the only remaining evidence. I re-establish the cor. in its original position as the cor. of secs. 29 and 30 only, as follows:
Set a slate stone 18x12x6 ins., 12" in the ground, for cor., marked with 5 notches on E. edge, from which
A Live Oak 4" dia., bears N.59½°E., 38 lks. dist. mkd. T30S R2W S29 BT.
A Fir 20" dia., bears N.75°W., 49 lks. dist. mkd. T30S R2W S30 BT.
Marks on old bearing tree referring to sec. 31 are sufficiently obliterated.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & W. Penley, crew - Dec. 19, 1967 - C.S. File 54/59-4

Found - No trace of corner stone, ground disturbed. Mound of stone found.
20" D.Fir now 36" stump, N.75°W., 32.3 ft., opened for scribe.
No trace of NE. BT.

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 2 W

S 30 | S 29

S 31

1967

New BTs- 9" Live Oak N.85°W., 5.4 ft. mkd. T30S R2W S30 CS BT
15" Live Oak S.80°E., 14.2 ft. mkd. T30S R2W S31 CS BT.

No trees to NE. in good condition.

This corner lies 58.1 ft. West of cor. for secs. 31 and 32 and approx. 320 North of Hwy. #227.

(Cont. Next Page)

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29 & 30 only, (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Wayne L. Rogers and Lance J. Bishop, Cadastral Surveyors, under Group #1132, surveyed May/June 1983 - (DCSO records Vol. 46 Page(s) 17788-89)

The Sec. cor., perpetuated and recorded by Powell in 1967, monumented with an iron post 1¼" dia., firmly set, projecting 10" above ground with brass cap mkd. in 1967, from which the remains of an original bearing tree:

A sawed Fir stump 34" dia., bears N.75°W., 49 lks. dist., with fragmentary scribe marks visible on opened blaze. and the remains of bearing trees mkd. by Powell:

A Live Oak 13" dia., bears S.81°E., 22½ lks. dist., with scribe marks S R2W CS visible on partially healed double blaze.

A Live Oak snag 6" dia., bears N.79°W., 8½ lks. dist., with scribe marks 30 S R2W S30 CS BT.

and new bearing trees:

A Fir 4" dia., bears N.63°E., 56 lks. dist. mkd. X BT.

A Fir 15" dia., bears N.34½°W., 81 lks. dist. mkd. T30S R2W S30 BT.

From this point, the United States Coast and Geodetic Survey Station H-500, bears S.81°27'E., 108.35 chs. dist., monumented with a brass tablet 3½" dia., set in concrete block, 2 ft. sq., with top mkd. UNITED STATES COAST AND GEODETIC SURVEY H 500 1949. The coordinates of this point were determined by the Douglas Co. Surveyors Office in 1975.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 12/6/2022 - C.S. File 67/55-14

Condition report only

BTs by Powell, 1967 -

Live Oak, S.81°E., now 14"

Live Oak, N.79°W., now gone

BLM BTs, 1983 -

Did not check

Found unrecorded BT -

A 27" D.Fir with healed blaze and tag nails, measures South 7.3 ft., now tagged and spiked.

Steel fence post approx. 3 ft. east.

Compass decl. 14½°E.