

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 201200

PRIMARY CORNER DESCRIPTION C C for Secs. 31 and 32 only (North)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6866)

Set a slate stone 18x10x5 ins., 12" in the ground for closing cor. of secs.31 and 32, marked C C on S. with 1 groove on S. and 5 grooves on E. face, from which
A Live Oak 12" dia., bears S.24°E., 17 lks. dist. mkd. T30S R2W S32 BT.
A Fir 12" dia., bears S.64½°W., 50 lks. dist. mkd. T30S R2W S31 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & W. Penley, crew - Dec. 19, 1967 - C.S. File 54/59-2

Found - 12" now 15" L.Oak S.24°E., 11.2 ft., opened for scribing, found scribe marks but not legible.
12" now 23" D.Fir S.64½°W., 33.0 ft., shows good scar.
No trace of stone, ground disturbed.
Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 2 W
CC S 29
S 31 | S 32
1967

New BT - 12" Live Oak S.29°E., 12.0 ft. mkd. T30S R2W S32 CC CS BT.
This corner lies 58.1 ft. East of cor. to secs. 29 and 30, and approx. 320 ft. North of Hwy. #227.

Bruce Shaner, L.S.. #430 - For: Roseburg Forest Products - Clem Berlier David Snyder- June 1995 - M 119-64 - C.S. File 63/161-36-B

Found - 1" I.P. with 2½" Brass Cap, from which:
15" Live Oak BT, now snag, bears S.24°E., 11.2 feet.
30" D.Fir BT (record 23", face overgrown, bears S.64½°W., 33.0'
12" Live Oak BT, now dead & down, scribes visible, bears S.29°E., 12.0 feet.
New BTs- 14" Live oak BT, I bark scribed "T30S R2W S32 BT", bears S.33°E., 14.3 feet.
6" D.Fir BT, I scribed "T30S R2W S 32 BT", bears S.68°E. 22.0 feet.
6' steel fence post, I set North, 1.0 feet.
Corner is 300 feet north of Canyonville - Trail Highway.

(Cont. Next Page)

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 201200

PRIMARY CORNER DESCRIPTION C C for Secs. 31 & 32 only (North)

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Fd. and used in BLM resurvey by Wayne L. Rogers and Lance J. Bishop, Cadastral Surveyors, under Group #1132, surveyed May/June 1983 - (DCSO records Vol. 46 Page(s) 17788)

Douglas Co. Surveyors Office - Crew: Stephen Flaue & Jeff Lorsung- 12/6/2022 - C.S. File 67/55-15

Condition report only
3 BTs found, good condition, BT tags good.
D.Fir S.64½°W., (OBT)
Live Oak, S.33°E., (Shaner)
D.Fir S.68°E., (Shaner)