

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Sec. 29 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6770)</p> <p>-----</p> <p>Set ¼ sec. post, from which A Fir 18" dia., bears N.53°E., 23 lks. A Laurel 12" dia., bears S.40°W., 8 lks.</p>
<p>GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6801 and 6808-09)</p> <p>-----</p> <p>(Page 6801) The ¼ sec. cor. partially obliterated. No trace is found of the post and the bearing trees are deeply overgrown. (Page 6808-09) I re-establish this corner in its original position as the ¼ sec. cor. on N. bdy. sec. 29 only, as follows: Set a slate stone 15x8x5 ins., 10" in the ground for ¼ sec. cor., marked ¼ on S. face, from which A Madrone 5" dia., bears S.10°E., 8 lks. dist. mkd. ¼ S29 BT. A Madrone 24" dia., bears S.40°W., 9 lks. dist. mkd. ¼ S29 BT. I destroy marks on former bearing tree referring to sec. 20.</p>
<p>Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - June 29, 1970 - C.S. File 54/73-71</p> <p>-----</p> <p>Found stone at ¼ corner, no marks visible, from which 24" Laurel now snag, S.40°W., 5.9 ft., opened for scribe. 5" Laurel now stump, S.10°E., 5.3 ft. Set Brass cap at cor. mkd: County Surveyors Office T 30 S R 2 W ¼ <u> </u> S 29 1970</p> <p>New BTs- 16" D.Fir S.65°W., 27.0 ft. mkd. ¼ S29 CS BT. 8" Laurel S.12°W., 34.2 ft. mkd. ¼ S29 CS BT. This corner lies 15.1 ft. West of ¼ cor. Sec. 20 only. (Rec. 27.7 ft.)</p>
<p>Fd. and used by BLM resurvey by Wayne L. Rogers and Lance J. Bishop, Cadastral Surveyors, under Group #1132, surveyed May/June 1983 - (DCSO records Vol. 46 Page(s) 17789-90)</p>
<p>continued next page</p>

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 239300

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Sec. 29 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2818, surveyed Nov. 2015 - (DCSO records Vol. 58 Page 23488 & Plat T30-2 2017-1)

The ¼ sec. cor. of sec. 29 only, monumented with an iron post, 1¼" dia., firmly set, projecting 14" above ground, with brass cap (properly) mkd.
from which the remains of an original bearing tree, reported by Rogers and Bishop in 1983

A sawed, decayed madrone stump, 16" dia., bears S.40°W., 5.9 ft., with no scribe marks visible on an open blaze. and the bearing trees mkd. by the Douglas County Surveyor's Office in 1970, reported by Rogers and Bishop

A madrone, 10" dia., bears S.11°W., 33.7 ft., with a healed blaze.

A fir, 24" dia., bears S.66°W., 27.1 ft., with a healed blaze.

From this cor., the 1/4 sec. cor. of sec. 20 only, bears S.87°26'58"E., 15.16 ft., monumented with an iron post, 1¼" dia., firmly set, projecting 14" above ground, with brass cap (properly) mkd.