

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6849)

Set a slate stone 18x10x10 ins., 12" in the ground for 1/4 sec. cor. marked 1/4 on W. face, from which
A Fir 15" dia., bears N.75°E., 21 lks. dist. mkd. 1/4 S4 BT.
A Fir 18" dia., bears S.11 1/2°W., 8 lks. dist. mkd. 1/4 S5 BT.

Survey by Bruce A. Shaner - For: National Plywood, Inc. - Wit: W. James and J. Griffin - July 12, 1060 - C.S. File 51/105-1

Orig. slate stone 18x10x10, 12" in ground, mkd. 1/4 on W. face, is missing. Two windfalls have recently slid over the area.
Record Fir 15" dia., bears N.75°E., 21 lks., mkd. 1/4 S 4 BT.
A rotten D.Fir stump with scribes visible was found here.
Record 18" Fir bears S.11 1/2°W., 7 lks., mkd. 1/4 S5 BT. A 10" Hemlock, dead and down mkd. 1/4 S5 BT, was found here.
I set a 3/4" Iron pipe for the 1/4 corner, from which
Pair of original BTs as described above, fit the correct description.
40" D.Fir scribed "1/4 S BT" bears N.69°E., 8.8 ft.
5" Yew scribed "1/4 S BT" bears S.46°30'W., 12.5 ft.

Douglas County Surveyors Office - Gary L. Langlitz, Deputy - Peter L Earle; James H Cook - Feb 3, 1976 - C.S. File 59/2-15

Found - 40" D.Fir stump scribed "1/4 S BT" on an unhealed face.
All other evidence of the orig. or resurvey corner and bearing trees has been destroyed.
At the corner point as determined by the above mentioned BT stump, 40" D.Fir bearing N.69°E., 8.8 ft., SET 1" x 30" Iron pipe, 24" in the ground with brass cap attached marked:
Douglas Co. Surveyor
T30S R2W
1/4
S 5 | S 4
1976
New BTs- A 12" Grand Fir bears S.35°E., 75.3 ft. scribed "1/4 S4 CS BT" on a double blaze.
A 16" Hemlock bears S.78°W., 60.7 ft. scribed "1/4 S5 CS BT" on a double blaze.

continued next page

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ron Quimby - Crew: N. Fromdahl & R Heichel- 9/2018 - C.S.
File 65/102-2

Found - DCSO brass cap (properly marked)
40" Fir stump (rotted) with open face N.69°E., 8.8
ft. no leg. scribes.
20" G.Fir S.35°E., 75.3 ft. good scar.
22" Hemlock S.78°W., 60.7 ft. good scar.
New - 10" W.Fir N.18°E., 13.2 ft. scribed ¼ S4 BT
5" Fir N.30°W., 22.0 ft. scribed X
Note - Compass decl. 15½°E.