

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 21

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6768)

-----  
Set ¼ sec. post, from which  
A Fir 36" dia., bears S.10°W., 62 lks.  
A Fir 18" dia., bears N.50°W., 79 lks.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6806)

-----  
This cor. is a Fir, 18" dia., and not a post as stated in the field notes. The SW. bearing tree is destroyed by fire. The other bearing tree and the cor. are deeply overgrown. I re-establish the cor. in its original position as follows: The original cor., a Fir 18" dia., for ¼ sec. cor., I mark ¼ S16 on N. and 21 on S. side, from which  
A Fir 24" dia., bears N.47½°W., 63 lks. dist. mkd. ¼ S16 BT.  
A Cedar 36" dia., bears S.66½°W., 75 lks. dist. mkd. ¼ S21 BT.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - Dec. 5, 1968 - C.S. File 54/73-64

-----  
Found - 18" now 30" Fir corner tree, shows good scars.  
24" Fir, now stump, N.47¼°W., 41.6 ft., shows scar.  
36" Cedar, now stump, S.66½°W., 49.5 ft., tree opened, scribe visible.

Set Brass cap at cor. mkd: County Surveyors Office  
T 30 S R 2 W  
¼ S 16  
S 21  
1968

New BTs- 17" D.Fir N.20°W., 23.3 ft. mkd. ¼ S16 CS BT.  
16" D.Fir S.5°E., 33.3 ft. mkd. ¼ S21 CS BT.