

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 16

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6766)

-----  
Marked a Laurel 10" dia., for ¼ sec. cor., from which  
A Fir 15" dia., bears S.20°E., 4 lks.  
A Laurel 12" dia., bears S.50°W., 25 lks.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page 6805)

-----  
The ¼ sec. cor. partially obliterated. The cor. tree is dead and ready to fall.  
I re-establish the cor. in its original position as follows:  
I uproot the dead cor. tree and in the cavity, Set a basalt stone 15x10x6 ins., 10" in the ground, for ¼ sec. cor., mkd. ¼ on W. face, from which  
A Fir 18" dia., bears S.20°E., 5 lks. mkd. ¼ S15 BT  
A Fir 20" dia., bears N.75°W., 16 lks., mkd. ¼ S16 BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: J.H. Markham - July 10, 1962 - C.S. File 42/421-20

-----  
Determined by O.B.T.s:  
25" Fir, uproot, N.75°W., 10.6 ft.  
20" Fir, snag, S.20°E., 3.3 ft.  
At corner point, Set 1/2" x 1/2" Angle iron, from which  
30" Cedar S.32°W., 40.7 ft. mkd. ¼ S16 BT.  
18" Fir N.80°E., 33.0 ft. mkd. ¼ S15 BT.  
50" Fir S.35°E., 21.7 ft. mkd. ¼ S15 BT.

Douglas Co. Surveyors Office - Vic Cangie; Clell Goodwin; Lenora Ladig - Dec. 17, 1975 - C.S. File 57/39-38

-----  
Found - 1" x 1" angle iron set by Markham, in place, at the corner.  
We find the remains of the only existing orig. BT, a rotten stump with scribing "BT" visible on rotting face, bears S.20°E., 3.3 ft.  
The original NW. bearing tree is gone.  
A 24" Incense Cedar (Rec. 30" dia.) alive with scribing partially visible on unhealed blaze, bears S.35°W., 40.7 ft. (Rec. S.32°W., 40.7 ft.) Markham BT.  
A 17" D.Fir (Rec. 18" dia.) alive with scribing visible on partially healed blaze, bears N.81½°E., 31.5 ft. (Rec. N.80°E., 33.0 ft.)

continued next page

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 16

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A 45" D.Fir (Rec. 50" dia.) with bark scribing visible, bears S.35°E., 20.1 ft. (Rec. S.35°E., 21.7 ft.)  
At the corner point, WE SET 1" x 30" Iron pipe with brass cap attached, marked: Douglas Co. Surveyor  
T 30 S R 2 W  
S 16 | S 15  
1/4  
1975  
We place angle iron alongside brass cap.  
This corner is located in a N-S fenceline approx. 150 ft. West of BLM Rd. #30-2-14.0