

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol 16 Pages 6843-4)

Set a basalt stone 15x8x8 ins., 10" in the ground for cor. of secs. 3, 4, 9 and 10, marked with 5 notches on S. and 3 notches on E. edge, from which

- A Cedar 7" dia., bears N.13½°E., 17 lks mkd T30S R2W S3 BT
- A Cedar 7" dia. bears S.18½°E., 9 lks mkd. T30S R2W S10 BT
- A Cedar 18" dia., bears S.36°W., 9 lks mkd. T30S R2W S9 BT
- A Fir 8" dia., bears N.23½°W., 17 lks. mkd. T30S R2W S4 BT

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: O.A. Keatley - March 24, 1960 - C.S. File 42/421-17

Determined by O.B.T.s:

- 36" Cedar S.36°W., 6.0 ft., found scribe.
- 7" dead Cedar S.15°E., 6.0 ft., found scribe.
- 9" Cedar N.13°E., 11.2 ft., found scribe.
- 16" Fir N.25°W., 11.2 ft.

At corner point, found stone and SET 1/2" x 30" Iron pipe, from which

- 12" Cedar S.31°E., 10.4 ft. mkd. S10 R2W BT.
- 24" Laurel N.82°E., 11.0 ft. mkd. S3 T30S R2W BT.
- 10" Cedar N.35°W., 19.8 ft. mkd.S4 R2W BT.

Douglas Co. Surveyors Office - Gary L. Langlitz; Peter Earle - Sept. 30, 1974 - C.S. File 57/8

Found - Stone and 1/3" I.P., both firmly set and in good condition at the corner point.

We find 3 original BTs in their proper position and mkd. as described in the orig. field notes. The orig. SE. BT is now dead and down.

We find 3 BTs in position and mkd. as described in 1960.

The area immediately NE. of the corner has been recently logged.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2232, Surveyed Oct. 2008/April 2009 - (DCSO records Vol. 57 Page(s) 22658-9)

The cor. of secs. 3, 4, 9, & 10, perpetuated by Markham, Jr., in 1960, monumented with an iron pipe, 22" long, 1" diam., firmly set, projecting 12" above ground, (alongside of which is a portion of the orig. basalt stone, 8x7x6") (Record, 15x8x8"), lying loose on the ground, with 5 notches on one face and 3 notches on an adjacent face), continued next pg

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

from which the remains of the orig. bearing trees
A cedar, 11" dia., bears N.13½°E., 11.2 ft., with a healed blaze.
A sawed cedar stump, 22" dia., bears S.36°W., 5.9 ft., with a decayed healed blaze and metal cover.
A fir, 23" dia., bears N.23½°W., 11.2 ft., with a healed blaze.
and bearing trees mkd. by Markham, Jr.
A madrone, 21" dia., bears N.78°E., 10.8 ft., with no marks visible on a partially healed blaze.
A cedar, 14" dia., bears S.31½°E., 10.2 ft., with scribe marks R2W S10 BT visible on a partially healed blaze.
A cedar, 19" dia., bears N.36¾°W., 20.3 ft., with a healed blaze.

At the corner point
Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

T30S		R2W	
S	4	S	3
S	9	S	10
2009			

from which
A fir, 7" dia., bears S.9½°W., 31.1 ft mkd. T30S R2W S9 BT
Bury orig. stone alongside, place iron pipe inside, and deposit a magnet in a white plastic case at the base of the stainless steel post.
Corner is located 1.0 ft. S.70°E. of a wooden fence post at the cor. of barbed wire fences extending S. and W.