

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6759)

Set post cor. secs. 26, 27, 34 and 35, from which
An Oak 9" dia., bears N.53°E., 110 lks.
An Oak 12" dia., bears S.78°E., 267 lks.
A Pine 15" dia., bears S.81°W., 433 lks.
A Fir 15" dia., bears N.89°W., 533 lks.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - Dec. 1968 - C.S. File 54/73-59

Found - 15" now 20" Sugar Pine S.81°W., 285.8 ft., scribe visible, BT scar, tree opened.
15" Fir, now stump, N.89°W., 351.8 ft., shows good scar.

No trace of NE. or SE. bearing trees.

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 2 W
S 27 | S 26
S 34 | S 35
1968

New BTs- 19" S.Pine N.5°W., 94.1 ft. mkd. T30S R2W S27 CS BT
12" D.Fir N.2°E., 103.0 ft. mkd. T30S R2W S26 CS BT
14" D.Fir S.81°E., 74.4 ft. mkd. T30S R2W S35 CS BT
Corner lies 15.0 ft. South of telephone line running NE-SW.

Jim Landrum; Leonard Herzstein, U.S. Forest Service (deputized by the County) - March 2, 1982 - C.S. File 61/32-8

Found - 2½" brass cap on 1" Iron pipe, firm, projecting 14", properly mkd., set by the DCSO.
Orig. 24" Ponderosa Pine, bears S.81°W., 285.8 ft., now snag, scribes visible "T30S R2W S34", on previously opened double blaze.

22" P.Pine bears N.5°W., 94.1 ft., partly healed blaze with fragmentary scribe marks visible.

14" D.Fir bears N.2°E., 103.0 ft., healed face, now snag.

16" D.Fir bears S.81°E., 74.4 ft., healed face.

10" D.Fir bears N.89°E., 132.5 ft., partly healed, double blaze. Scribes visible "T30S R2W S26 BT". Brass washer with stamp "536" nailed to lower face. BT tag marked by Baughman 2/78. BT not of record. This BT scarred by recent road building.

New BT - 20" Ponderosa Pine bears S.88°W., 108.6 ft. scribed "T30S R2W S34 CS BT" on double blaze.

(Cont. Next Page)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Painted 6" red band and painted blazes on all BTs and added 54-4 attention signs to BTs.
Corner now located ± 150 ft. South of new road.

Fd. OK, July 1994 by G. Lang - M 120-69

Jonathan B. Drew, II, USFS - Assisted by: Andrew Hellman & Jacob Hunt - 9/7/2016 - C.S. File 65/93-55

Found - A 1½" galvanized iron pipe with a 2½" brass cap (properly mkd), projecting 13" above the ground.
No trace found of a (9" oak) 1857, (N.53°E., - 72.6 ft) 1857
No trace found of a (12" oak) 1857, (S.78°E., 176.2 ft) 1857
No trace found of a (15" pine) 1857, (S.81°W., 285.8 ft) 1857
No trace found of a (15" fir) 1857, (N.89°W., 351.8 ft) 1857
A 28" pine bears, N.5°23'W., 94.3 ft, with a healed single blaze, (N.5°W., 94.1 ft) 1968
A root hole brs N.0°48'E., 101.9 ft an indeterminate size fir log lays southeast with no marks visible, (N.2°E., 103.0 ft) 1968
A 20" fir bears, S.82°56'E., 74.2 ft, with a healed single blaze, (S.81°E., 74.4 ft) 1968
A 24" fir bears, N.89°04'W., 132.4 ft, with a healed double blaze, (N.89°E., 132.5 ft) 1981
A root hole bears, S.89°55'W., 108.5 ft., a 23" pine log lays south with a healed single blaze, (S.88°W., 108.6 ft) 1981

New - A 12" fir brs S.29°28'W., 39.6 ft., mkd "T30SR2WS34" "BT" on a double blaze.
New BTs include a 3/4" brass washer marked "ORALS #89396" nailed in the lower blaze between the "B" & "T" scribe.

Method of measurement - LEICA 1103+ total station, BTs measured to an aluminum nail set at side center, w/bearings to center. Bearing of S.89°17'14"E., per M65-56, held on center of wood 4"x4" post east of corner, 133.8 ft to west face.

Note - Clear brush from around monument and to BTs. Tie flagging to monument and guard posts, paint BT faces & a 6" band at head height.
Lat: N.42°55'52.727" Long: W.122°55'21.337"
Source: Post processed resource grade, as reported by Jack Snyder. Datum: NAD83