

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6762)

Set 1/4 sec. post, from which
An Oak 10" dia., bears N.80°E., 65 lks.
A Pine 48" dia., bears N.7°W., 71 lks.

GL0 survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6799 and 6812-13)

(Page 6799)
No trace of the 1/4 sec. cor. is found after careful search.
(6812-12)
Point midway between secs. cors.
Set a porphyry stone 12x10x7 ins., 8" in the ground for 1/4 sec. cor. mkd. 1/4 on W. face, from which
A Yellow Pine 10" dia., bears S.45°E., 9 lks. dist. mkd. 1/4 S14 BT.
A Madrone 18" dia., bears S.45°W., 32 lks. dist. mkd. 1/4 S15 BT.

BLM resurvey by C. Albert White, Cadastral Surveyor, under Group #524, surveyed Aug/Sept. 1963 - (DCSO records Vol. 32 Page(s) 13416-17)

The 1/4 sec. cor., monumented with an unmarked conglomerate stone, 10x10x6 ins., loosely set 6" in the ground, from which the bearing trees mkd. by Mensch in 1909:

Rotted wood and stump hole of a Pine, bears S.45°E., 9 lks. dist., with the pitch face of the original blaze, mkd. 1/4 S14 BT, lying beside the hole.

A Madrone snag 15" dia., bears S.49°W., 32 lks. dist., mkd. S BT, and other illegible scribe marks on an opened blaze. (Rec. brg. S.45°W.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

1/4
S 15 | S 14
T 30 S R 2 W
1963

from which new bearing trees:

AFir 13" dia., bears S.19°E. 36 lks. dist., mkd. 1/4 S14 BT

A Fir 19" dia., bears S.72°W. 58 lks. dist., mkd. 1/4 S15 BT

Deposit the conglomerate stone alongside the iron post.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Douglas County Surveyor's Office, Randall Smith, Stephen Flause - Oct 27, 1994 - C.S. File 64/58-5

Found - 3¼" Brass cap on a 2½" O.D. iron pipe, loosely set, protrudes 21" above ground. BC/IP leans 18" south of plumb. (1963 BLM)

Unmarked 10"x10"x6" conglomerate stone found loose along southwest edge of BC/IP (orig.?)

Note: Evidence of ground being disturbed in area around corner position of fd. BC/IP. Does not fit well with remaining BT/s. We calculate a position for corner based on remaining BT's. Top of brass cap shows evidence of being hit. Accessories Found - (brg. & dist. taken from position determined from BT's)

18" now rotted 5 ft. high Madrone stub. No marks visible. Bears S.49°W., 21.1 ft. (agrees with 1963 BLM) Orig. BT.

Original southeast Pine now gone.

13" now 19" dia. D.Fir with a fully healed double blaze, bears S.19°E., 23.8 ft. (agrees with record) 1963 BLM

19" now 23" dia. down D.Fir with a fully healed single blaze. Root hole is large and indefinite. (rec. S72°W., 38.3 ft.) 1963 BLM

Position of loose BLM BC/IP is referenced with a 5/8" x 32" long iron rod with a DCS0 alum cap marked "B0 1 1995". Iron rod protrudes 4" above ground.

1963 BLM brass cap iron pipe measures 28" long is set at a point determined from remaining bearing trees. The marks "RESET 1995 DCS0" are added. BC/IP now protrudes 8" above ground.

New Accessories -

9" dia. D.Fir double blazed and scribed "¼ S14 CS BT" bears S.74½°E., 19.4 ft. to center of root crown.

4" dia. D.Fir double blazed and scribed "X BT" bears S.60°W., 9.4 ft.

5/8" iron rod with a DCS0 alum. cap marked "B0 1 1995" bears S.8½°E., 6.4 ft.

Corner lies on a steep south slope in a north-south fence line.

Brent Knapp - For: Roseburg Resources Co. - 2/2022 - M180-72

Found - 3" brass cap

Rotten Madrone stump, indeterminate size, S.49°W., 21.1'

19" D.Fir S.19°E., 23.8', healed double blaze with tag. Continued next page

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

18" D.Fir S.74½°E., 19.4', healed scar.
10" D.Fir, S.60°W., 9.4', healed scar.
5/8" iron rod with DCS0 alum. cap mkd: "B0 1 1995"
S.8½°E., 6.4'