

PRIMARY CORNER DESCRIPTION C C for Secs. 30 & 31, West bdy.

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 6875)

-----  
Set a post, cor. of secs. 25, 30, 31 and 36, from which  
A Red Fir 40" dia., bears S.45°E., 30 lks. dist.  
A Red Fir 25" dia., bears N.30°E., 13 lks. dist.  
A Red Fir 25" dia., bears N.20°W., 8 lks. dist.  
A Laurel 8" dia., bears S.25°W., 9 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 16 Page(s) 6893) and (Vol. 17 Page 7028)

-----  
The post, set for this cor. is gone, but all of the Fir bearing trees are standing and easily identified by their marks namely

A Fir 48" dia., mkd. T30S R3W S31 BT.  
A Fir 30" dia., mkd. T30S R3W S30 BT.  
A Fir 30" dia., mkd. T30S R4W S25 BT.

A clump of small Laurels are growing in sec. 36, corresponding in direction and distance described in the field notes furnished me. I restore this cor. by setting a Laurel post, 4½ ft. long, 4" dia., 24" in the ground, mkd. T30S S30 on the NE.; R3WS31 on the SE.; R4W S36 on the SW.; S25 on NW. faces, with 5 notches on N. and 1 notch on S. edges, from which

A Fir 30" dia., bears N.30°E., 13 lks. mkd. T30S R3W S30 BT.  
A Fir 48" dia., bears S.45°W., 30 lks. dist. mkd. T30S R3W S31 BT.  
A Fir 20" dia., bears S.41°W., 55 lks. dist. mkd. T30S R4W S36 BT.  
A Fir 30" dia., bears N.30°W., 13 lks. dist. mkd. T30S R4W S25 BT.

The bearing trees in secs. 30, 31 and 25 are the old bearing trees which I freshly marked, old marks being dim.

GLO survey by William F. Briggs, U.S. Deputy Surveyor, under special instructions dated Aug. 7, 1891 - (DCSO records Vol. 17 Page(s) 7100)

-----  
Cor. to secs. 30 and 31, T30S R3W bears N.1°75'E., 27.67 chs. (from Sec. cor. 25 & 36, T30-4) as established by W. Thiel. Post and BT standing.

(Cont. Next Page)

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION C C for Secs. 30 & 31 only, West bdy.

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6969)

-----  
The cor. to secs. 30 and 31, 4 lks. East of my line, which is a post, 4" sq., firmly set mkd. T30S S30 on NE.; R3W S31 on SE. faces, with 5 notches on N. and 1 notch on S. edges. The marks are destroyed on the SW. and NW. faces, from which

A Fir 30" dia., bears N.30°E., 13 lks. dist. mkd. T30S R3W S30 BT.

A Fir 48" dia., bears S.45°E., 30 lks. dist., mkd. T30S R3W S31 BT.

I find 2 trees West of this line which agree in kind, size, direction and distance, with the field notes furnished me, but the marks have been destroyed and this being a cor. to secs. 30 and 31 only, I do not restore the marks.

Ben B. Irving, Deputy Co. Surveyor - Wit: John A. Irving; V.N. Poole; Joe Wright; Walter Poole - Feb. 1930 - C.S. File 37/18 and M 1-37

-----  
Location identified from three original BTs which I reblaze and scribe in the bark. Set an 8" x 6" x 24" white quartz rock for corner and Yew wood post along side 3" x 6" x 24", scribed S30 CS on NE. face and T30S R3W S31 on SE. face.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel crew - March 1963 - C.S. File 52/138-50

-----  
Found - Stone at corner. Three orig. BTs. Also scribed stake, all as recorded.

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 3 W

| S 30

| S 31

1963

Rescribed orig. 36" now Red Fir, N.30°E., 10.0 ft. "S30 T30S R3W CS BT".