TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 120540

PRIMARY CORNER DESCRIPTION Center West 1/16 Cor., Section 7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by John Jelley, Cadastral Surveyor, Group #599, surveyed Sept. 1965 - (DCSO records Vol. 33 Page(s) 13916)

Point for the center W 1/16 sec. cor. of sec. 7
Set an iron post 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

C $\frac{\text{W 1/16}}{\text{S 7}}$ C
1965

from which
A Cedar 6" dia., bears N.66°W., 102 lks. dist. mkd. C W 1/16 S7 BT.
A Fir 8" dia., bears S.79°E., 72½ lks. dist. mkd. C W 1/6 S7 BT.

Douglas County Surveyors Office - L.E. Monrean; P.L. Earle, crew - Nov. 2, 1976 - C.S. File 59/26-4

Found - 1965 BLM brass cap properly marked, approx. 4" above ground, firmly set.
6" now 11" Cedar bears N.64°W., 66.1 ft. (Rec. N.66°W.., 67.3 ft.) Tree has well healed blaze.
8" now 13" Fir, bears S.78°W., 47.2 ft. (Rec. S.79°E., 47.8 ft.) Tree has a well healed blaze.
Iron pipe (Rec. S.57°E., 15.2 ft. set by Thompson in 1956, not found.