

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 178100

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. Sec. 6 only, T31-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. -  
Wit: R.G. Boyd - July 27, 1960 - C.S. File 42/392-64

-----  
At corner point, Set 2" x 30" I.Pipe, from which  
8" Chinquapin, N.18°E., 20.0 ft. "¼ S6 BT"  
6" Chinquapin, S.74°E., 25.0 ft. "¼ S6 BT"  
4" Fir S.43°E., 23.8 ft. "¼ S6 BT"

Douglas Co. Surveyors Office - John M. Powell, Frank Jones &  
Joe Brady, crew - Jan. 1966 - C.S. File 52/63-43

-----  
Found - Iron pipe at ¼ corner.  
8" Chinquapin, now 9", N.18°E., 20.0 ft. scribed ¼  
S6 BT.  
6" Chinquapin now 7", S.24°E., 25.0 ft. scribed ¼ S6  
BT.  
4" D.Fir now 5", S.43°E., 23.8 ft. scribed ¼ S6 BT.

Set brass cap alongside iron pipe, mkd:  
County Surveyors Office

¼  $\frac{T\ 30\ S}{S\ 6}$  R3W  
T 31 S  
1966

All BTs in good condition. Corner is at cutting corner.

Fd. and Used in BLM Resurvey by Boyd W. Peterson and Dale T.  
Bedell, Cadastral Surveyors, Under Group #'s 1277 & 1315,  
Surveyed Sept. 1985/August 1986 - (DCSO records Vol. 48  
Page(s) 18322)