

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 200340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6878-79)

-----  
Set ¼ sec. post, from which  
A Chinquapin 18" dia., bears S.2°E., 103 lks. dist.  
A Fir 30" dia., bears N.30°W., 36 lks. dist.

Douglas Co. Surveyors Office - George Wenderoth - Aug. 1950/April 1951 - C.S. File 40/269

-----  
1" I.Pipe, from which  
16" Fir S.28°E., 29.6 ft.  
14" Madrona S.88°15'W., 33.0 ft.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: May 1952 - C.S. 41/52-1

-----  
Set from original BT. Found 1½" Iron pipe, from which  
A Fir 14" bears S.27°E., 35.0 ft., already marked "¼ S BT"  
10" Laurel bears West, 34.0 ft. mkd. "¼ S BT".

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Jan. 1963 - C.S. File 52/138-11

-----  
Found - 1½" Iron pipe.  
14" Fir S.27°E., 35.0 ft., OK, scar.  
10" Laurel, West 34 ft., dead. Scribed.  
New BT - 5" Fir S.76°W., 20.2 ft. scribed "¼ S19 CS BT".

BLM resurvey by Wayne L. Rogers; Lance J. Bishop; James L. White, Cadastral Surveyors, under Group #1133 - Surveyed June 7, 1983/Dec. 12, 1984 - (DCSO records Vol. 47 Page(s) 17859-60)

-----  
The ¼ sec. cor., perpetuated and recorded by Wenderoth in 1950, and further perpetuated and recorded by Byron in 1963, monumented with an iron pipe, 1½" dia., firmly set, projecting 3" above ground, from which the remains of an original bearing tree  
A sawed Fir stump 55" dia., bears N.30°W., 36 lks. dist., no marks visible.  
and the remains of bearing trees mkd. by Wenderoth  
A Fir 28" dia., bears S.26 ¾°E., 45 lks. dist., with healed double blaze.  
(Cont. Next Page)

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 200340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 20

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A Madrone snag 14" dia., bears S.88½°W., 53 lks. dist., with fragmentary scribe marks visible on open decayed double blaze.  
and a bearing tree mkd. by Byron  
A Fir 9" dia., bears S.78 3/4°W., 31 lks. dist. with healed double blaze.  
At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, directly over the iron pipe with brass cap mkd: T 30 S R 3 W  
1/4  
S 19 | S 20  
1983

BLM resurvey by A. Bert Skeesick Cadastral Surveyor & Robert H. Browning, Surveying Tech. under Group #2000, 2100, & 2300, surveyed Nov. 2004/Feb. 2005 - (DCSO rec. Vol. 55 Page(s) 21501-4) & Plat 2008-1

-----  
The ¼ sec. cor. of secs. 19 & 20, monumented with an iron post, 2½" dia., firmly set, projecting 4" above the ground, with brass cap mkd. as reported as Rogers, et al in 1983-84; from which the remains of an orig. BT  
A root hole bears N.30°W., 23.8 ft. no trunk remains.  
and the remains of a BT reported by Rogers, et al  
A burnt & decayed fir snag, 14" dia., bears S.26¾°E., 29.7 ft. with fragmentary scribe marks visible on a partially healed blaze.  
and new accessories  
A rebar, 30" long, 5/8" dia., driven 27" in the ground for a reference monument, bears S.45°E., 7.50 ft. with aluminum cap mkd. RM ¼ S20 7.50 FT TO COR 2004 and an arrow pointing to the cor.  
A rebar, 30" long, 5/8" dia., driven 27" in the ground for a reference monument, bears S.45°W., 7.50 ft. with aluminum cap mkd. RM ¼ S19 7.50 FT TO COR 2004 and an arrow pointing to the cor.  
Corner is located N.60°W., 4.0 ft. of a 4 strand barbed wire fence, with fences extending east & south. Corner is also located South, 15.5 ft. of a dirt road, 12 ft. wide, which bears N.50°E., & S.50°W.