

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6974-75)

Set an Oak post 4 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S. on W. face, from which
An Oak 11" dia., bears N.9°W., 76 lks. dist. mkd. ¼ S BT
An Oak 11" dia., bears N.57°E., 66 lks. dist. mkd. ¼ S BT

George J. Wenderoth - Wit: Fred Seymour - 1951 - C.S. File 41/16

Found 1" Iron pipe, from which
14" Oak N.9°E., 50.2 ft.
14" Oak N.57°E., 43.6 ft., badly damaged.
Scribe: 14" Oak N.68°E., 46.5 ft.

Survey by Robert M. Thompson - Feb. 11, 1956; April 1, 1956 - C.S. File 42/173

Found bent pipe and 3 BTs.
Set 1" I.Pipe at corner, beside old bent pipe.
Old BT described as N.9°E., is actually N.9°W.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #599, surveyed Sept. 1965 - (DCSO records Vol. 33 Page(s) 13911-12)

The ¼ sec. cor., perpetuated and recorded by Thompson in 1956, monumented with a bent iron pipe, 1" dia., firmly set, extending 6" above ground, with an iron pipe 1" dia., firmly set, extending 20" above ground, from which the original bearing trees:

A W.Oak 16" dia., bears N.57°E., 67 lks. dist., with opened blaze, no marks visible. (Rec. 66 lks.)

A W.Oak 16" dia., bears N.11°W., 76 lks. dist., with healed blaze. (Rec. N.9°W.)

and a bearing tree mkd. by Wenderoth in 1951:

A W.Oak 16" dia., bears N.68°E., 71 lks. dist., with healed double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

T 30 S R 3 W

¼

S 7 S 8

1965

Deposit the iron pipe alongside the iron post.