

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6956)

-----  
Set a Fir post 4 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. marked ¼ S. on W. face, from which  
A Fir 8" dia., bears S.27¼°E., 41 lks. dist. mkd. ¼ S BT  
A Fir 8" dia., bears S.19½°W., 21 lks. dist. mkd. ¼ S BT

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. -  
Wit: R.G. Boyd - June 9, 1960 - C.S. File 42/392-56

-----  
Determined by O.B.Ts:  
20" Fir S.27°E., 27.1 ft.  
16" Fir S.19°W., 13.9 ft.  
At corner point, Set 3/4" x 30" I.P., from which  
50" Cedar S.78°E., 29.5 ft. "¼ S33 BT"  
8" Fir N.42°W., 10.9 ft. "¼ S32X BT"  
7" Fir N.40°E., 15.3 ft. "¼ S33 BT"  
12" Laurel S.88°E., 32.6 ft. "¼ S33 T30S R3W BT"

BLM Admin. survey found I.P., June 1980. See BLM for records.

BLM resurvey by A. Bert Skeesick Cadastral Surveyor & Robert H. Browning, Surveying Tech. under Group #2000, 2100, & 2300, surveyed Nov. 2004/Feb. 2005 - (DCSO rec. Vol. 55 Page(s) 21501-4) & 2008-1 thru 2008-4 Plats

-----  
The ¼ sec. cor. of secs. 32 & 33, perpetuated by Markham in 1960 monumented with an iron pipe 28" long 1" dia., firmly set, projecting 8" above the ground, from which the remains of the orig. BTs  
A fir snag, 23" dia., bears S.27¼°E., 27.1 ft. with no marks visible.  
A sawed & decayed fir stump, 37" dia., bears S.19½°W., 13.9 ft. with no marks visible.  
and the remains of BTs mkd. by Markham  
A sawed & burnt fir stump, 8" dia., bears N.40°E., 15.3 ft. with fragmentary scribe marks visible on partially healed blaze.  
A sawed & burnt cedar stump, 37" dia., bears S.78°E., 29.5 ft. with no marks visible.  
A sawed & burnt fir stump, 15" dia., bears N.42°W., 10.9 ft. with a healed blaze.  
At the corner point  
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

continued next page

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

T30S R3W  
1/4  
S 32 | S 33  
2005

from which

A fir, 5" dia., bears S.35°E., 21.7 ft., mkd: 1/4 S33 BT.

A fir, 5" dia., bears S.56°W., 12.8 ft., mkd: 1/4 S32 BT.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

All new BTs have a 2 1/2" x 1/4" nail driven at the base on right side center.

BLM Dependent resurvey by Timothy J Moore, Cadastral Surveyor and Robert H. Browning, Survey Tech, under Group No. 2127 surveyed Feb/April 2006- (DCSO records Vol. 57 Pages 22514-5)

-----  
The 1/4 sec. cor. of secs. 32 & 33, monumented with a stainless steel post, 2 1/2" dia., firmly set, projecting 4" above the ground, with brass cap (properly) mkd.

from which the remains of original bearing trees

A fir snag, 23" dia., bears S.27 1/4°E., 27.1 ft., with no marks visible.

A sawed and decayed fir stump, 37" dia., bears S.19 1/2°W., 13.9 ft., with no marks visible.

and the remains of bearing trees mkd. by Markham, in 1960

A sawed and burnt cedar stump, 37" dia., bears S.78°E., 29.5 ft., no marks visible.

A sawed and burnt fir stump, 15" dia., bears N.42°W., 10.9 ft., with a healed blaze.

and bearing trees mkd. by Skeesick and Browning

A fir, 5" dia., bears S.35°E., 21.7 ft., with scribe marks 1/4 S33 BT visible on open blaze.

A fir, 6" dia., bears S.56°W., 12.8 ft., with scribe marks 1/4 S32 BT visible on open blaze.