

PRIMARY CORNER DESCRIPTION Sec Cor for 9, 10, 15 and 16

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Pgs 6946-47)

-----  
Set a Cedar post 5 ft. long, 5" sq., 24" in the ground, for cor. to secs. 9, 10, 15 and 16, marked T30S S10 on NE.; R3W S15 on SE.; S16 on SW.; and S9 on NW. faces, with 3 notches on E. and 4 notches on S. edges, from which

A Fir 14" dia., bears N.60°E., 14½ lks. dist., mkd. T30S R3W S10 BT.

A Laurel 7" dia., bears S.10½°E., 33 lks. dist. mkd. T30S R3W S15 BT.

A Fir 14" dia., bears S.20½°W., 76 lks. dist. mkd. T30S R3W S16 BT.

A Laurel 10" dia., bears N.61 3/4°W., 44 lks. dist. mkd. T30S R3W S9 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Feb. 1963 - C.S. File 52/138-25

-----  
Found - Orig. 14" now 14" Fir S.20½°W., 50.2 ft., shows scribing.

Orig. 14" now 24" Fir N.60°E., 9.6 ft., shows scar Line tree 6.0 ft. North of corner, as recorded.

Orig. 7" now 7" Laurel S.10½°E., 21.8 ft., shows scars.

Orig. NW. BT, not found.

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 3 W

S 9 | S 10

S16 | S 15

1963

New BTs- Rescribe now 7" Laurel S.10°E., 21.5 ft. "S15 CS BT"

Rescribe now 24" Fir N.61°E., 10.0 ft. "S10 T30S R3W CS BT"

22" R.Fir bears S.11°W., 51.2 ft. scribed S16 T30S R3W CS BT.

36" R.Fir bears North 5.5 ft. scribed S9 T30S R3W CS BT.

Fd. and used in BLM resurvey by Stephen D. Albright and Jack W. Bowder, Cadastral Surveyors, under Group #776, surveyed June/July 1972 - (DCSO records Vol. 36 Page(s) 14982)

Fd. Ok by Greg Lang, 1/2007 - M152-13