

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6952)

Set a stone 12 x 11 x 5 ins., 8" in the ground for 1/4 sec. cor. marked 1/4 on W. face, from which
A Laurel 6" dia., bears N.77 1/2°W., 27 lks. dist. mkd. 1/4 S BT.
A Fir 3" dia., bears N.89°E., 16 lks. dist., mkd. 1/4 S BT.

BLM Resurvey by Lynn M. Roseberry, Cadastral Surveyor - Under Group #599 Surveyed, Oct. 26, 27, 1967 - (DCSO records Vol. 34 Page(s) 14061)

The 1/4 sec. cor., monumented with the original conglomerate stone, 9 x 7 x 6 ins., loosely set 2" in the ground, mkd. 1/4 on W. face, from which the original bearing trees:
A Fir 21" dia., bears N.89°E., 10 lks. dist., mkd. with a healed blaze. (Rec. 16 lks.)
A Madrone stump hole and clump of Madrone sprouts, bears N.77 1/2°W., 27 lks. dist.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 30 S R 3 W
1/4
S 4 S 3
1967
from which a new bearing tree
A Fir 13" dia., bears S.44 1/2°W., 13 lks. dist. mkd. 1/4 S4 BT
Deposit the original stone alongside the iron post.