

PRIMARY CORNER DESCRIPTION Sec Cor for 1, 2, 11 and 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6926)

-----  
Set a Cedar post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 1, 2, 11 and 12, mkd. T30S S1 on NE.; R3W S12 on SE.; S11 on SW.; and S2 on NW. faces, with 1 notch on E. and 5 notches on S. edges, from which

A Fir 11" dia., bears N.11°E., 111 lks. dist. mkd. T30S R3W S1 BT.

A Fir 40" dia., bears S.18 3/4°E., 106 1/2 lks. dist. mkd. T30S R3W S12 BT.

A Fir 36" dia., bears S.28 1/2°W., 52 1/2 lks. dist. mkd. T30S R3W S11 BT.

A Fir 24" dia., bears N.39°W., 70 lks. dist. mkd. T30S R3W S2 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Jan. 1963 - C.S. File 52/138-2

-----  
Found all orig. BTs. All check record and show scars.  
Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 3 W  
S 2 | S 1  
S 11 | S 12  
1963

New BTs- 13" R.Fir bears S.45°W., 8.4 ft. scribed S11 T30S R3W CS BT.

12" R.Fir bears South, 19.1 ft. scribed S12 T30S R3W CS BT.

14" R.Fir bears N.88°E., 14.2 ft. scribed S1 T30S R3W CS BT.

10" R.Fir bears N.86°W., 40.3 ft. scribed S2 T30S R3W CS BT.

Ron Quimby - Crew: N. Fromdahl, R Heichel & R Vincent - 1/2018 - C.S. File 65/101-19

-----  
Condition report

Found - DCSO brass cap (properly mkd)

20" Fir S.45°W., 8.4 ft. good scar.

16" Fir South 19.1 ft. good scar.

28" Fir N.88°E., 14.2 ft. good scar.

18" Fir N.86°W., 40.3 ft. good scar.

8" Cedar S.35°E., 40.0 ft vis scribes BLM 11/15/2017

Note - Compass decl. 15 1/2°E.

continued next page

PRIMARY CORNER DESCRIPTION Sec Cor for 1, 2, 11 and 12

Alias	Description

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2896, surveyed Nov 2017/Dec 2019- (DCSO records Vol. 59 Page 23796-7 & Plat T30-3 2020-1)

-----  
The cor of secs. 1, 2, 11, & 12, perpetuated by Byron, in 1963; monumented with an iron post, 1¼" dia., firmly set, projecting 14" above ground, with a brass cap (properly) mkd. from which the remains of the original bearing trees

A fir snag, 36" dia., bears N.11°E., 73.3 ft. with a healed blaze.

A sawed decayed fir stump, 60" dia., bears S.18¾°E., 70.3 ft. with a healed blaze.

A fir snag, 36" dia., bears S.28½°W., 34.7 ft., with a healed blaze.

A sawed decayed fir stump, 56" dia., bears N.39°W., 46.2 ft., with a healed blaze.

and the remains of the bearing trees mkt by Byron

A fir, 30" dia., bears N.87¼°E., 14.5 ft., with a healed blaze.

A decayed fir stump, size indeterminate, bears S.2¼°E., 19.4 ft., alongside of which is a down decayed fir, 20" dia., no marks visible.

A fir, 22" dia., bears S.44°W., 8.0 ft., with a healed blaze.

A fir, 24" dia., bears N.86¾°W., 40.1 ft., with a healed blaze.

and a new bearing tree

A cedar, 8" dia., bears S.30¼°E., 40.0 ft, mkd. T30S R3W S12 BT