

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6927)

-----  
Set a stone 16 x 14 x 5 ins., 12" in the ground, for 1/4 sec. cor. mkd. 1/4 on N. face, from which

A Fir 28" dia., bears S.25 1/4°E., 68 lks. dist. mkd. 1/4 S BT

A Fir 8" dia., bears N.60°E., 64 lks. dist. mkd. 1/4 S BT.

-----  
Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Jan. 1963 - C.S. File 52/138-3

-----  
Found - Stone at corner.

Orig. 28" now 34" Fir N.25 1/4°E., 44.9 ft., shows good scar.

Orig. 8" BT, now down, shows scribing.

Set brass cap alongside cor. stone, mkd:

County Surveyors Office

T 30 S R 3 W

1/4  $\frac{S \ 1}{S \ 12}$

1963

New BT - 8" Fir N.33°E., 21.0 ft. scribed 1/4 S1 CS BT.

-----  
Douglas Co. Surveyors Office - John M. Powell; Randall Smith, crew - May 19, 1983 - C.S. File 62/7-10

-----  
Found - Orig. stone, out of ground, mkd. 1/4.

1963 DCSO brass cap out of ground, cap properly mkd.

28" D.Fir now 35" bears S.25 1/4°E., 44.9 ft., shows good scar. (Recorded in 1963, N.25 1/4°E., 44.9 ft.)

8" D.Fir now down and rotted, bears N.60°E., 42.2 ft. (This bearing and dist. to hole where tree stood)

8" D.Fir now 13", bears N.33°W., 21.0 ft. shows good scar. (Record in 1963, N.33°E., 21.0 ft.)

Reset brass cap at 1/4 cor. by using 3 good distances and 2 orig. bearings. by changing quadrants from 1963, everything fits. Stamped "RESET 1983" on cap.

Re-tagged all bearing trees.

This corner lies on SE slope approx. 140 ft. West of draw.

-----  
Ron Quimby - Crew: N. Fromdahl, R Heichel & R Vincent - 1/2018 - C.S. File 65/101-17

-----  
Found - Stone approx. 16"x14"x5"

13" Fir stump N.31°11'W., 21.3 ft. (rec. N.33°W., 21.0 ft.)

continued next page

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

40" Fir S.25°30'E., 41.1 ft (Rec. S.25¼°E., 44.9 ft)  
New bearing and dist. to set cor. These trees were  
shot with instrument being almost opposite of  
each other - dist do not work used stone.  
Set - 2½" alum. cap on 5/8"x30" I.Rod alongside stone mkd:  
ROSEBURG RESOURCES COMPANY  
T30S R3W  
¼  $\frac{S.1}{S12}$   
2018  
LS 1654  
New - 10" D.Fir S.57°W., 21.2 ft. scribed ¼ S12 BT  
4" D.Fir N.22°E., 24.5 ft. scribed ¼ S1 BT  
10" D.Fir N.80°E., 23.5 ft. scribed ¼ S1 BT  
Note - Compass decl. 15¼°E.