

PRIMARY CORNER DESCRIPTION N NW Cor. Jacob Slippy DLC #37

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - GLO survey by Bowman and Burnett, under Contract dated Sept. 1855 (DLC survey)

Set a post marked, from which
A W.Oak 12" dia., bears S.25°E., 70 lks.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (Pg. 690 DLC volume)

Exterior angle corner. The old post marked T30S R4W C1 37 set for this corner was standing, but decayed. I replace the same by setting an Oak post 4½ ft. long, 4" sq., 24" in the ground, marked T30S R4W C. 37 on E. face, from which
A W.Oak 12" dia., bears S.25°E., 70 lks. dist. mkd. T30S R4W C. 37 BT. This is the original bearing tree, whose marks being dim, I renew.

Ben B. Irving - Wit: L.H. Smick; Huron Clough; J.L. Worthington - Feb. 5-7, 1927 - Vol. 3 Pg. 273 and C.S. File 3/63

I identify the location of this corner by a 14" B.Oak. The Govt. field notes call for a 12" W.Oak S.25°E., 70 lks. The B.Oak when chopped out carried the old scribe marks in excellent condition although rot was beginning to show. I renewed this corner by driving a 1" x 36" Iron bar 30" in the ground and an Oak post 3" x 36" marked D.L.C. 37 C.S., from which
A B.Oak bears S.61°E., 72.5 ft. mkd. D.L.C. 37 C.S. B.T.

Douglas Co. Surveyors Office - James Byron - Mike Darby and M. Godfrey, crew - Aug/Sept. 1963 - C.S. File 53/26

Found - 1" Iron rod at corner.
Now 8" B.Oak S.60°E., 72.5 ft. Open and find scribing.
Orig. SE. BT, not found, falls in old logging road.
New BTs -Rescribe now 8" B.Oak S.60°E., 72.5 ft. "NW Ext. L DLC 37 CS BT".
15" Pine bears N.57°W., 9.5 ft. scribed "NW Ext. L DLC 37 CS BT".
Corner of fences to N. and E. bears N.70°E., 6.0 ft.