

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 6 and 7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 7007)

-----  
Set ¼ sec. post, at proper dist., from which  
A B.Oak 6" dia., bears S.15°W., 80 lks. dist.  
A Laurel 6" dia., bears N.10°E., 75 lks. dist.

GL0 survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7095)

-----  
The old post is gone, but the Oak in Sec. 7 marked ¼ S BT, is standing. I restore this corner by setting a W.Oak post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on W. face, from which  
A B.Oak 10" dia., bears S.15°W., 80 lks. dist. mkd. ¼ S BT. This is the original bearing tree, whose mark being dim, I renew.  
A Fir, 12" dia., bears N.15°W., 17 lks. dist. mkd. ¼ S BT.

Ben B. Irving - Wit: L.H. Smick; Huron Clough; J.L. Worthington - Feb. 1927 - C.S. File 3/63; Vol. 3 Pg. 273

-----  
I identify the location of this corner by two old bearing trees as follows:  
A 20" Fir mkd. ¼ S. BT, N.29°W., 17 lks. The brg. of this tree as given in the govt. field notes is N.15°W.  
A 10" B.Oak mkd. ¼ S BT, S.15°W., 80 lks.  
I renewed this corner by setting a ½" x 1" x 24" Iron bar 20" in the ground and a W.Oak post 3" x 36" in the ground.  
As old B.Oak BT is badly rotted I marked:  
An 18" Fir S.6°W., 21 ft. "¼ S7 CS BT".

T.R. Eslinger, Surveyor - Feb. 2, 1951 - C.S. File 40/299-1

-----  
1/2" x 1" x 20" bar could not be found.  
1/2" x 34" copperweld rod, 3" out of ground set for corner from two old BTs and original post, from which  
10" B.Oak S.15°W., 52.8 ft.  
12" Fir, much larger now, N.15°W., 11.2 ft.  
24" Fir double blaze, South 20'± added 8/15/2024 JC

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - Aug. 1963 - C.S. File 53/26-92

-----  
Found - 1/2" Iron pipe on ground and out of place.  
Orig. 12" now 30" R.Fir, N.15°W., 11.2 ft, shows scars.  
22" R.Fir S.6°W., 21.0 ft., shows good scars. (Cont.)

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 6 and 7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found - Remains of orig. SW. BT.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 30 S R 4 W  
¼ S 6  
S 7  
1963

E-W fence 11 ft. North.

Fd. & used by Ronald Quimby - April 1999 - M 129-44