

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 6992)

Set post at average distance for cor. of secs. 19, 20, 29 and 30, from which

- A W.Oak 10" dia., bears N.60°W., 48 lks. dist.
- A W.Oak 6" dia., bears N.20°E., 42 lks. dist.
- A W.Oak 20" dia., bears S.15°W., 139 lks. dist.
- A B.Oak 15" dia., bears S.55°E., 155 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7081)

The post set for secs. 29, 30, 19 and 20, having decayed, but all the bearing trees described in the field notes furnished me, are standing, I restore this corner by setting a W.Oak post, 4 ft. long, 4" sq., 24" in the ground marked T30S S20 on NE.; R4W S29 on SE.; S30 on SW.; S19 on NW. faces, with 2 notches on S. and 5 notches on E. edges, from which

- A W.Oak 12" dia., bears N.20°E., 42 lks. dist. mkd. T30S R4W S20 BT.
- A B.Oak 30" dia., bears S.60°E., 150 lks. dist. mkd. T30S R4W S29 BT.
- A W.Oak 28" dia., bears S.7°W., 132 lks. dist. mkd. T30S R4W S30 BT.
- A W.Oak 14" dia., bears N.56°W., 46 lks. dist. mkd. T30S R4W S19 BT.

These are the old bearing trees described in the field notes, which I re-mark, as the old marks are overgrown.

Fd. and tied in GLO survey by Wm. M. Bushey under contract #620, dated June 17, 1893 - (DCSO records, Vol. 17 Page 7120)

Survey by John H. Markham, Jr. - Wit: B.E. Blomgren - For: Stomar Lumber Co. - C.S. File 41/161-2

Determined from old bearing trees:

- A 15" W.Oak snag bears N.20°E., 30.0 ft., found old scribe
- 35" B.Oak windfall bears S.60°E., 105.0 ft., found scribe
- W.Oak 20" bears N.56°W., 30.0 ft.

At corner point, Set 1" x 20" axle with 6" flange up, from which

- B.Oak 40" dia., bears N.26°W., 49.0 ft. mkd. S19 BT.
- 10" W.Oak bears N.73°E., 33.3 ft. mkd. S20 BT.
- 12" W.Oak bears S.28°E., 73.3 ft. mkd. S29 BT.
- W.Oak, 30" bears S.57°W., 137.0 ft. mkd. S30 BT.

A fence runs N. and S. from corner.

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - June/July 1963 - C.S. 53/26-63

Found - All bearing trees OK, as recorded.
1" x 20" axle with 6" flange has been disturbed by
cat cleaning line for fence.

Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 4 W
S 19 | S 20
S 30 | S 29
1963

Fence N. and S., 6 ft. East.

Fd. OK, July 1991 - M 113-36

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2872, surveyed April 2017/Oct. 2019- (DCSO records Vol. 59 Page 23851-2)

The cor. of secs. 19, 20, 29, & 30, perpetuated by Markham in 1953; subsequently perpetuated by Byron, in 1963; monumented with an iron post, 1¼" dia., firmly set bent over with top flush with the surface of the ground, with a brass cap (properly) mkd.

from which the remains of the original BTs

A roothole bears N.20°E., 27.7 ft., alongside of which is a down decayed oak snag, 15" dia., no marks visible.

An oak, 27" dia., bears N.56°W., 30.4 ft., with a healed blaze.

and the remains of the BTs mkd. by Markham

A decayed oak snag, size indeterminate, bears N.73¼°E., 33.3 ft., with a healed blaze.

An oak, 42" dia., bears N.24¼°W., 48.8 ft., with a healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

T30S R4W
S19|S20
S30|S29
2017

from which

An oak, 13" dia., bears S.2¾°E., 76.9 ft., mkd. T30S R4W S29 BT.

An oak, 4" dia., bears S.20°W., 5.7 ft., mkd. X BT.

Bury the iron post, 32" long, alongside the stainless steel post.