

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 7005)

Set 1/4 sec. post, from which
A W.Oak 15" dia., bears S.10°W., 450 lks. dist.
A B.Oak 12" dia., bears S.17°E., 350 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7089-90)

The old post is gone and both bearing trees have been cut down, but the stump of B.Oak, 18" dia., corresponding in size and direction with the description in filed notes, is standing in Sec. 17 showing the letters BT. The marks on the stump of the W.Oak tree are obliterated. I restore this corner by setting a W.Oak post, 40" long, 4" sq., 24" in the ground, marked 1/4 S on W. face, from which
A W.Oak 36" dia., bears S.21°E., 5.90 chs. dist. mkd. 1/4 S BT.
A W.Oak 6" dia., bears S.27°W., 3.22 chs. dist. mkd. 1/4 S BT.

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCSO records Vol. 52 Page(s) 20119)

Point for the 1/4 sec. cor. of secs. 17 & 18, at proportionate dist., determined by the irregular boundary method between the original cor. of secs. 17, 18, 19 & 20 and the reestablished NW cor. of DLC #42, there is no remaining evidence of the original corner.
Set a stainless steel post, 28" long, 2 1/2" diam., 40" in the ground, with brass cap mkd.
T30S R4W
1/4
S 18 S 17
1994
Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.
The corner is located in the center of a graveled road, 20 lks. wide, bears N. and S.