

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 7005)

Set ¼ sec. post, at average dist., made trench and drove a charred (charred?) stake in the center as per instructions.
G. McNair's house, S.27°W.
McNair's house, S.67°E.
John Weaver's house, S.77°E.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7091)

Set a Cedar post, 4 ft. long, 4" sq., 24" in the ground, marked ¼ S on N. face, raised a mound of stone alongside. The old post is gone, cultivation has obliterated all marks on the ground.

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCSO records Vol. 52 Page(s) 20122)

Point for the ¼ sec. cor. of secs. 8 & 17, at proportionate dist., there is no remaining evidence of the original corner. Set a stainless steel post, 28" long, 2½" diam., 52" the ground, with brass cap mkd. T30S R4W
¼ S 8
 S 17
 1995

No suitable accessories available
Deposit white "DEEP-1" magnetic markers at base of and on top of stainless steel post.
The corner is located in a pasture. A small drainage ditch bears S., 0.58 chs. dist., ditch drains N.10°E.; same ditch also bears E., 0.18 chs. dist., ditch drains N.40°E.