

PRIMARY CORNER DESCRIPTION Center N 1/16 Sec. 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCSO records Vol. 52 Page(s) 20144)

Point for the center N 1/16 sec. cor. of sec. 5.
Set a stainless steel post, 28" long, 2½" diam., 27" in the ground, with brass cap mkd.

C
N1/16 S 5
C
1994

from which

A cedar, 16" diam. bears S.7½°E. 60 lks. mkd. CN1/16 S5 BT
A fir, 9" diam. bears N.73½°W., 29 lks., mkd. CN1/16 S5 BT
Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - Oct. 26, 1998 - C.S. File 66/4-6

Found - A 3¼" dia., brass cap on a 2½" O.D. by 30" long bent stainless steel pipe is brought into DCS Office by Greg Lang. (1994 BLM)

"DEEP-1" magnetic marker was located 12" below newly graded cat road. (1994 BLM)

16" now 18" dia., I.Cedar with an unhealed single blaze scribing visible " CN 1/16 S5 BT" bears S.7½°E., 39.6 ft. (Agrees with rec.) 1994

9" now 11" dia., D.Fir, with a partially healed single blaze scribing visible "16 S5 BT" bears N.73½°W., 19.1 ft. (Agrees with rec.) 1994

Set - 5/8" by 30" long iron rod is driven alongside found magnetic marker. Set 2" below cat road surface.

4" dia., D.Fir, double blazed and scribed "X BT", bears N.77½°E., 17.9 ft.

2 3/8" brass cap on a 1 3/8" O.D. by 32" long iron pipe protrudes 9" above ground bears North 15.0 ft. mkd: DOUGLAS COUNTY

T 30 S R
C N 4
1 1/16 W
C
SOUTH 15'
1998
SURVEYORS

Corner falls along easterly edge of cat road.