

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 6999)

-----  
Set ¼ sec. post, from which  
A W.Oak 36" dia., bears S.7°E., 537 lks. dist.  
A W.oak 30" dia., bears S.85°W., 514 lks. dist.  
Dumore's house, S.65°W.  
George Day's house N.8°E.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7065)

-----  
¼ Sec. Cor. post of this corner is gone, but both bearing trees are standing. I restore this corner by setting a Fir post, 3 ft. long, 3" sq., 24" in the ground, marked ¼ S on W. face, from which  
A W.Oak 40" dia., bears S.7°E., 537 lks. dist. mkd. ¼ S BT. This is the old bearing tree, whose marks I renew. The other bearing tree I find to bear S.5°E. and not S.85°W., as given in the field notes.  
I mark a B.Oak 15" dia., S.13°W., 506 lks. dist. mkd. ¼ S BT.

H.L. Eppstein, County Surveyor - Wit: William Rachor; Henry Rachor; N.E. Richardson - Oct. 26, 1928 - Vol. 3 Pg. 288-89; M 4-45

-----  
This corner was gone. So I set it proportional distance and bearing between sec. corners by placing 1" x 18" galv. Iron pipe 10" under ground and marked new witness trees:  
A 22" W.Oak S.46°E., 916 lks.  
A 5" Prune tree S.15°30'W., 572 lks.