

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 17 Page(s) 7112)

Set a stone 15x8x8 ins., 10" in the ground, for 1/4 sec. cor., mkd. 1/4 on N face, from which

A Laurel, 10" dia., bears N.26°W., 60 1/2 lks., mkd: 1/4 S BT.

A Maple, 10" dia., bears S.47 1/2°E., 50 1/4 lks., mkd: 1/4 S BT.

Bruce Shaner - For: Roseburg Resources Co. - July 2000 - C. S. File 65/30-19P & M 132-37

USBLM Cadastral Surveyor proportioned this in, in 1999. Though still not officially recorded we used it in sec. 34 survey. (signed) BAS

Found - 3 1/4" brass cap on 2 1/2"x28" steel pipe, cap mkd:

US BUREAU OF LAND MANAGEMENT

T30S R4W

1/4 S 27
S 34

1999

from which

22" D.Fir, scribed "1/4 S27 BT" bears N.0 1/4°E. 20.1 ft.

12" D.Fir, scribed "1/4 S34 BT" bears S.54°W. 17.9 ft.

12" D.Fir, scribed "1/4 S BT" bears N.76°E., 18.8 ft.

16" D.Fir, scribes "1/4 S BT" bears N.89°w., 33.0 ft.

6' steel fence post bears East, 1.0 ft.

Note - Corner is 254 ft. East of USBLM Rd. #28.1

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group #1907, surveyed July 1999/Aug. 1999. (DCSO rec. Vol. 53 page(s) 20653)

Point for the 1/4 sec. cor. of secs. 27 & 34, at proportionate dist., there is no remaining evidence of the original corner. Set a stainless steel post, 28" long, 2 1/2" dia., 25" in the ground, with brass cap mkd. T 30 S R 4 W

1/4 S 27
S 34
1999

from which

A fir, 22" dia., bears N.0 1/4°E., 20.1 ft., mkd. 1/4 S27 BT.

A fir, 12" dia., bears S.54°W., 17.9 ft., mkd. 1/4 S34 BT.
Deposit a magnet in a white plastic case at the base of the stainless steel post.