

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 6999)

Set 1/4 sec. post average distance, from which
A W.oak 15" dia., bears N.80°W., 55 lks. dist.
A B.Oak 10" dia., bears S.25°W., 62 lks. dist.

GL0 survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7063)

A post is standing in place, marked 1/4 S., and both the bearing trees are standing. I restore this cor. by replacing the old and partially decayed post, by an Oak post, 3 ft. long, 3" sq., 24" in the ground, marked 1/4 S on N. face, from which
A W.Oak 20" dia., bears N.78 1/4°W., 55 lks. dist. mkd. 1/4 S BT.
A B.Oak 15" dia., bears S.19°W., 62 lks. dist. mkd. 1/4 S BT
These are the old bearing trees, whose marks being dim, I renew.

G.G. Stewart, Deputy Co. Surveyor - Wit: Montgomery, Morgan, Moore and Beals - Dec. 29, 1922 - Vol. 3 Pg. 136; M 2-9; and C.S. File 7/31

Reset from two original BTs, standing, one rotted.
Drove an Iron pipe and stake. Remarkd a 20" W.Oak of O.B.T.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - June 1963 - C.S. File 53/26-57

Found - Orig. 20" now 26" W.Oak N.78 1/4°W., 36.3 ft., shows scribe marks.
Orig. 15" now 30" B.Oak S.19°W., 41.0 ft., shows good scar.
Iron pipe set by Stewart not found. We do find base of old stake.

Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 4 W
1/4 S 10
S 15
1963

Rescribe now 30" B.Oak S.19°W., 42.2 ft. "1/4 S15 CS BT".
1/4 Cor. bears S.62°W., 8.0 ft. from a fence corner, fences running North and East.

Fd. OK, Jan. 1990 by K. DeGroot - M 109-47

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 3/24/1999 - C.S. File 66/8-24

Found - 2½" dia. brass cap on a 1½" o.d. iron pipe ,
 protrudes 6" above ground. 1963
 15" now 27" dia. W.Oak with a previously opened
 rotted blaze no marks visible , bears N.78¼°W.,
 36.3 ft. OBT
 10" now 29" dia. B.Oak with a fully healed double
 blaze, bears S.19°W., 43.0 ft. (rec. per 1963
 ren. S.19°W., 42.2 ft.) OBT
New - 15" dia. D.Fir double blazed and scribed "¼ S15 CS
 BT" bears S.76°W., 21.4 ft.
 9" dia. D.Fir double blazed and scribed "¼ S10 CS
 BT" bears N.46°E., 29.4 ft.
Corner lies at the intersection of a 4-way fence corner.

Fd. Ok by R. Quimby 1/2007 - 2007-0016 A&B
Fd. Ok by R. Quimby 7/2008 - M159-41
Fd. Ok by D. Edwards 10/2025 - 2025-0027 B