

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 23

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #1070, surveyed June 1981/May 1982 - (DCSO records Vol. 43 Page(s) 16822)

-----  
Point for the center 1/4 sec. cor. of sec. 23, at intersection with the E. and W. center line.  
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:  
T 30 S R 4 W  
C 1/4 S 23  
1981

from which  
A Fir 24" dia., bears N.60°E., 45½ lks. dist. mkd. C ¼ S23 BT.  
A B.Oak 28" dia., bears S.½°W., 25 lks. dist. mkd. C ¼ S23 BT.

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Mike Koch - 9/12/2020 (Filed 3/17/2020) - C.S. File 67/46-24

-----  
Found - A 2½" dia. iron post by Jelly, in 1981, firmly set, projecting 1" above the ground with a 3¼" dia. brass cap marked as follows:

BTs by Jelley 1981 -  
A 34" dia. D.Fir bears N.60°E., 30.0 ft. with a healed blaze.  
A root hole bears S.1/2°W., 16.5 ft. with a 26" dia. x 3' tall rotted B.Oak stump with a healed blaze alongside and out of position.  
New BTs- A 10" W.Oak bears N.8½°E., 24.0 ft. scribed "C¼ S23" "CS BT"  
A 7" Maple bears S.2°E., 18.9 ft. scribed "C¼ S23 CS" "BT"  
A 12" Madrone bears S.82°W., 4.0 ft scribed "C¼ S23" "CS BT"

Note - All bearing trees have BT tags attached. All new bearing trees have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to the side and center of the root crown.  
Monument falls near the top of a moderate NE slope in a mixed wooded area of oak, maple, madrone, fir and cedar and 35 ft. east of a driveway.  
Compass decl. 15°E.