

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 541700

PRIMARY CORNER DESCRIPTION Sec Cor for 35 & 36 only, T29-4

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6360)

Set a post at proper distance, cor. of secs. 1, 2, 35 and 36, from which

- A Laurel 20" dia., bears S.20°E., 74 lks. dist.
- A Laurel 14" dia., bears N.15°E., 10 lks. dist.
- A Laurel 12" dia., bears N.60°W., 36 lks. dist.
- A Laurel 8" dia., bears S.45°W., 50 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 15 Page(s) 6399-6400)

The post set for this corner is gone, but all the bearing trees are still standing and easily identified by their marks. I restore this corner by setting a Fir post 4½ ft. long, 4" sq., 24" in the ground mkd: T29S R4W on N. face; S36 on E.; S35 on W. faces, with 1 notch on E. and 5 notches on W. faces, from which

- A Laurel 18" dia., bears N.15°E., 10 lks. dist. mkd. T29S R4W S36 BT.
- A Laurel 15" dia., bears N.66°W., 36 lks. dist. mkd. T29S R4W S35 BT.

These are the bearing trees described in the field notes of the original survey, all of which I remarked. I destroyed mark of bearing trees in Secs. 1 and 2.

F.C. Frear, Deputy Co. Surveyor - Wit: Marrison; Safely; H. Wilson; C.J. Wilson - Oct/Nov. 1918 - C.S. File 7/18; M 1-3; Vol. 3 Pg. 29-30 and Field book 14=45

Renew this corner from old BTs.
Set in 1" x 36" I.P. and 4" x 48" Cedar stake, from which

- A 12" Fir bears N.13½°E., 20 lks.
- A 48" Cedar bears S.32°W., 9 lks.

Douglas Co. Surveyors Office - May 1963 - C.S. 52/126-133

Found 1" I.P. at corner and both BTs as recorded by Frear in 1918. We add "BT" in wood to 48" Cedar S.32°W., 6.0 ft.

Fd. Ok by David Edwards - Jan 2005 - M 147-18