

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 35 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 6987)

Set ¼ sec. post, from which
A Red Fir 12" dia., bears S.27°W., 38 lks. dist.
A Laurel 11" dia., bears N.43°E., 36 lks. dist.

((NOTE: The above corner by Ford must be in doubt due to statement by Thiel in Vol. 17 Pg. 7025 and several other pages) - "There is no post or bearing trees to be found, even not a blaze, although there are plenty of Firs around. This confirms the statement of Mr. Briggs, County Surveyor, who has lived at Canyonville for over 35 years, that Deputy Ford did not run this line; neither the South bdy. as he has never discovered any marks. - - - -" (V. Laugen, March 1996)

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7029)

A Fir 40" dia., which I mark ¼ S on W. face for ¼ sec. cor., from which
A Fir 24" dia., bears N.22°E., 53 lks. dist. mkd. ¼ S BT
A Laurel 3" dia., bears S.5°W., 10 lks. dist. mkd. ¼ S BT

Cor. tied and used in GLO Survey by Wm. M. Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 - (DCSO records, Vol. 17 Page 7110)

Survey by John M. Markham, Jr. - Wit: R.G. Boyd - For: Stomar Lumber Co. - Feb. 22-24, 1959 - C.S. File 42/356-9

Determined by O.B.T.
At corner point, found 50" Fir snag, bark scribed "¼S" on West face and Set ¾" x 30" Iron pipe, from which
40" Fir bears N.22°E., 35.0 ft. (O.B.T.)
12" Laurel bears N.7°W., 26.5 ft. mkd. ¼ S35 T30S R4W BT.
7" Laurel bears S.81°E., 17.6 ft. mkd. ¼ S36 BT.
8" Fir bears S.43°W., 13.9 ft. mkd. ¼ S35 BT.
(Closing corner for secs. 35 & 36 bears South 381.0 ft.)