

PRIMARY CORNER DESCRIPTION C C for Secs. 30 & 31 only, T30-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 6875)

Set a post, cor. of secs. 25, 30, 31 and 36, from which
A Red Fir 40" dia., bears S.45°E., 30 lks. dist.
A Red Fir 25" dia., bears N.30°E., 13 lks. dist.
A Red Fir 25" dia., bears N.20°W., 8 lks. dist.
A Laurel 8" dia., bears S.25°W., 9 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 16 Page(s) 6893) and (Vol. 17 Page 7028)

The post, set for this cor. is gone, but all of the Fir bearing trees are standing and easily identified by their marks namely

A Fir 48" dia., mkd. T30S R3W S31 BT.
A Fir 30" dia., mkd. T30S R3W S30 BT.
A Fir 30" dia., mkd. T30S R4W S25 BT.

A clump of small Laurels are growing in sec. 36, corresponding in direction and distance described in the field notes furnished me. I restore this cor. by setting a Laurel post, 4½ ft. long, 4" dia., 24" in the ground, mkd. T30S S30 on the NE.; R3WS31 on the SE.; R4W S36 on the SW.; S25 on NW. faces, with 5 notches on N. and 1 notch on S. edges, from which

A Fir 30" dia., bears N.30°E., 13 lks. mkd. T30S R3W S30 BT.
A Fir 48" dia., bears S.45°W., 30 lks. dist. mkd. T30S R3W S31 BT.
A Fir 20" dia., bears S.41°W., 55 lks. dist. mkd. T30S R4W S36 BT.
A Fir 30" dia., bears N.30°W., 13 lks. dist. mkd. T30S R4W S25 BT.

The bearing trees in secs. 30, 31 and 25 are the old bearing trees which I freshly marked, old marks being dim.

GLO survey by William F. Briggs, U.S. Deputy Surveyor, under special instructions dated Aug. 7, 1891 - (DCSO records Vol. 17 Page(s) 7100)

Cor. to secs. 30 and 31, T30S R3W bears N.1°75'E., 27.67 chs. (from Sec. cor. 25 & 36, T30-4) as established by W. Thiel. Post and BT standing.

(Cont. Next Page)

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 700228

PRIMARY CORNER DESCRIPTION C C for Secs. 30 & 31 only, T30-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6969)

The cor. to secs. 30 and 31, 4 lks. East of my line, which is a post, 4" sq., firmly set mkd. T30S S30 on NE.; R3W S31 on SE. faces, with 5 notches on N. and 1 notch on S. edges. The marks are destroyed on the SW. and NW. faces, from which

A Fir 30" dia., bears N.30°E., 13 lks. dist. mkd. T30S R3W S30 BT.

A Fir 48" dia., bears S.45°E., 30 lks. dist., mkd. T30S R3W S31 BT.

I find 2 trees West of this line which agree in kind, size, direction and distance, with the field notes furnished me, but the marks have been destroyed and this being a cor. to secs. 30 and 31 only, I do not restore the marks.

Ben B. Irving, Deputy Co. Surveyor - Wit: John A. Irving; V.N. Poole; Joe Wright; Walter Poole - Feb. 1930 - C.S. File 37/18 and M 1-37

Location identified from three original BTs which I reblaze and scribe in the bark. Set an 8" x 6" x 24" white quartz rock for corner and Yew wood post along side 3" x 6" x 24", scribed S30 CS on NE. face and T30S R3W S31 on SE. face.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel crew - March 1963 - C.S. File 52/138-50

Found - Stone at corner. Three orig. BTs. Also scribed stake, all as recorded.

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 3 W

| S 30

| S 31

1963

Rescribed orig. 36" now Red Fir, N.30°E., 10.0 ft. "S30 T30S R3W CS BT".