

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 700528

PRIMARY CORNER DESCRIPTION C C for Secs. 7 & 18 only, T30-3

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6972)

-----  
At point of intersection, I set a stone 14 x 12 x 8 ins., 10" in the ground, for closing cor. to secs. 7 and 18, marked C C on E. face, with 2 notches on N. and 4 notches on S. edges, from which,

- A Fir 36" dia., bears N.23 3/4°E., 14 lks. dist. mkd. T30S R3W S7 BT.
- A Fir 15" dia., bears S.43 1/2°E., 17 lks. dist. mkd. T30S R3W S18 BT.
- A Fir 11" dia., bears N.51°W., 45 3/4 lks. dist. mkd. T30S R3W CC S7 and 18 BT.

Survey by Robert M. Thompson - Feb/Apr. 1956 - C.S. File 42/173

-----  
At this corner (cutover on all sides):  
Found 3 BT stumps, some scribing visible.  
Old NW BT is a rotted stump with scribe visible.  
NE BT, a 40" D.Fir stump.  
SE BT, a 20" D.Fir snag.  
I renew this corner as follows:  
Set 3/4" I. Pipe.  
From which 2 new trees:  
7" I.Cedar N.58°11'E., 42.7 ft.  
17" D.Fir N.38°55'W., 80.4 ft.

BLM resurvey by John Jelley, Cadastral Surveyor, under Group #599, surveyed Sept. 1965 - (DCSO records Vol. 33 Page(s) 13908)

-----  
True point for the closing cor. of secs. 7 and 18.  
Set an iron post 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd. T 30 S T 30 S  
S 12 | S 7 CC  
S 18 | S 18  
R 4 W R 3 W  
1965

- from which
- A Fir 16" dia., bears N.62 1/2°E., 120 lks. dist. mkd. T30S R3W S7 CC BT.
  - A Fir 18" dia., bears S.44 1/2°E., 209 lks. dist. mkd. T30S R3W S18 CC BT.

From this point the original closing cor. of secs. 7 and 18, bears S.85°19'W., 0.55 chs. dist., perpetuated and recorded (Cont. Next Page)

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 700528

PRIMARY CORNER DESCRIPTION C C for Secs. 7 & 18 only, T30-3

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

by Thompson in 1956, monumented with an iron pipe, 1" dia., firmly set, extending 3" above ground, from which the original bearing trees:

A sawed Fir stump 38" dia., bears N.23 3/4°E., 14 lks. dist. mkd. T30S R3 S on opened blaze.

A Fir snag 22" dia., bears S.43½°E., 17 lks. dist. with opened and burned blaze.

A rotted Fir stump 14" dia., bears N.53°W., 45 3/4 lks. dist. mkd. 30 R3W 7 on section of blaze lying beside stump. (Rec. N.51°W.)

and bearing trees marked by Thompson

A Cedar 12" dia., bears N.56½°E., 66 lks. dist. mkd. T30S R3W S7 BT on partly healed double blaze.

A Fir 19" dia., bears N.41°W., 121 lks. dist. mkd. 30 R3W BT on partly healed double blaze.

From this same point, the angle point bet. secs. 12 and 18 bears S.2°17'W., 8.85 chs.

David Edwards - For: Swanson Group, INC - 4/2007 - M152-75  
-----

Found - BC

1965 BLM BTs fall in road area & are gone.

14" Cedar by Thompson bears N.0°24'E., 21.1', with healed blaze.

Fir stump bears N.57°W., 105.5'

Set - 6' steel post N.2°E., 2 ft.