

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 17 Page 7148)

-----  
Set a post corner of secs. 20, 21, 28 and 29, from which  
A W.Oak 20" dia., bears S.60°E., 44 lks.  
A B.Oak 10" dia., bears N.68°E., 63 lks.  
A B.Oak 4" dia., bears N.45°W., 90 lks.  
A B.Oak 12" dia., bears S.45°W., 170 lks.

E. Summers - For: Bollenbaugh Estate - April 2, 1920 - (Could find no record source for this language except in "old" Cor. Bk. Pg. 146, probably from survey recorded in Vol. 3 Pg. 68)

-----  
Reset from old BTs. Set stone from new BTs:  
A Laurel 8" dia., bears N.11°00'W., 11 lks.  
A W.Oak 5" dia., bears N.65°00'W., 23 lks.  
A Laurel 10" dia., bears S.55°30'E., 14 lks.  
A Laurel 11" dia., bears S.21°00'W., 36 lks.

Doug. County Surveyors Office - James W. Byron, Deputy - Mike Darby; Jim Halterman - Oct./Nov. 1963 - C.S. File 53/26-32

-----  
Found - Orig. SE and SW BTs, alive, show scars.  
Orig. NW BT., now stump. NE BT, now snag.  
Also find BTs and Stone as recorded by Summers except do not find NW BT.  
Set Brass cap at cor. mkd: County Surveyor's T30S R5W S20 | S21  
Office, 1963 S29 | S28  
New BTs -7" R.Fir bears S.80°E., 6.0 ft. scribed S28 T30S R5W CS BT.  
8" R.Fir bears S.28°E., 33.6 ft. scribed S28 T30S R5W CS BT.  
8" Laurel bears S.52°W., 38.0 ft. scribed S29 T30S R5W CS BT.  
5" W.Oak bears N.44°E., 16.2 ft. scribed S21 CS BT.  
Corner is on the ridge 40 ft. South of old logging road and 75 ft. West of fence.

Doug. County Surveyors Office - Clell Goodwin, Deputy - Gary Langlitz; Vic Cangie; Lenora Ladig - Oct. 16, 1975 - C.S. File 57/36-21

-----  
Found - 1963 DCSO brass cap on a 1" x 30" I.P.  
22" (possible orig. 20") Oak tree, alive and scarred but hollow bears S.56°E., 31.8 ft. (Call: S.60°E., 29.0 ft.) (Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

11" Madrone with visible scribe "S 20 CSBT", alive but hollow bears N.8½°W., 7.2 ft. (Call: N.11°W., 7.2 ft.)  
6" Oak, alive and well healed bears N.44°E., 16.2 ft  
10" Fir snag bears S.74°E., 6.2 ft. (Call: S.80°E., 6.0 ft.)  
13" Madrone with scribed face rotted out, bears S.53°E., 9.1 ft. (Call: S55½°E., 9.2 ft.)  
9" Fir snag, bears S.28°E., 33.6 ft.  
10" Madrone, alive and well healed bears S.52°W., 38.0 ft.  
New BTs -13" Fir bearing N.86°W., 59.0 ft. mkd. "T30S R5W S20 CS BT" in a double blaze.

---

Fd. Brass cap as per record, R. Brown, May 1993, M 112-76 ABC  
Fd. brass cap & BOs, Nov. 1996 by R. Wytcherley, 1997-0019  
Fd. Ok by Kris DeGroot, 4/2006 - M 146-38 & M146-45  
Fd. OK, July 2007 by R. Brown - M146-59

---

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Oct. 12, 2012 - C.S. File 67/36-31  
-----  
Condition report only  
Found - The 1920 stone (no description of size) not found. Stones are around base of BC monument but none are marked.  
A 2½" dia., brass (properly mkd) on a 1" I.D. iron pipe is firmly and plumbly set protruding 15" dia., above low rough mound of stone. 1963  
A possible root hole is fd close to bearing & dist. of the NE BT. OBT  
A W.Oak 20" dia., now a 24" dia., W.Oak with a rotted center (no blazing or scribing remains) bears S.56°E., 31.8 ft.(rec. S.60°E., 29.0 ft., this dist. is close to face meas) OBT  
A B.Oak, 12" dia., now a 25" dia., B.Oak with a previously opened, now fully healed, blaze; bears S.45°W., 114.3 ft. (rec. S.45°W., 112.2 ft.) OBT  
A B.Oak now a low rotted oak stub; bears N.45°W., 59.4 ft. (as per rec.) OBT  
A laurel 10" dia., now a 1 ft tall 15" dia., madrone stump with no blaze evidence; bears S.55½°E., 9.2 ft. (as per rec.) 1920  
An 11" laurel now a 3 ft long 14" dia., madrone stump with a possible rotted out blaze scar is tipped out and fallen (orig. position indiscernible) 1920  
continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A W.Oak 5" dia., now an 8" dia., B.Oak with a possible healed blaze (very faint); bears N.65°W., 14.7 ft. (rec. N.65°W., 15.2 ft.) 1920  
A laurel 8" dia., now a 12" dia., madrone with an unhealed rotted-out double blaze; bears N.8½°W., 7.3 ft. (rec. N.11°W., 7.3 ft.) 1920  
A 5" W.Oak, now an 8" dia., W.Oak with a fully healed double blaze; bears N.44°E., 16.2 ft. (as per rec) 1963  
A 7" R.Fir now a mostly rotted away fallen D.Fir but with blaze faces still intact reading "T30S R5W S28 CS" "BT"; lies near record B & D but has no remaining root hole. 1963  
An 8" R.Fir now a D.Fir (same description & scribing as for previous Fir but with intact root crown) bears S.28°E. 33.6 ft (as per rec) 1963  
An 8" laurel now a 16" dia., madrone with a fully healed double blaze; bears S.48°W., 38.6 ft. (rec. S.52°W., 38.0 ft.) 1963  
A 13" Fir now a 25" dia., D.Fir with a fully healed double blaze; bears N.86°W., 59.0 ft. (as per rec) 1975  
New - All found BTs are tagged to reflect changed measurement.  
Note - Monument is on flat ground near summit off broad high ridge approx. 75 ft. West from an N-S fence line and in a mixed forest of Oak, Madrone & Fir. Compass decl. 15½°E.

Fd. BC as per rec. 9/2017 by R. Brown M171-34