

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 & 16

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 17 Page 7147)

-----  
Set a post corner of secs. 9, 10, 15 and 16, from which  
A B.Oak 12" dia., bears N.22°E., 67 lks.  
A B.Oak 10" dia., bears N.37°W., 69 lks.  
A Laurel 8" dia., bears S.68°W., 100 lks.  
A W.Oak 15" dia., bears S.43°E., 36 lks.

Corner not found or the witness trees, as fire has destroyed the timber in the supposed locus of this corner. - by Oscar F. Thiel, under Contract #658 dated May 21, 1896 (DCSO records, Vol. 17 Page 7173)

-----  
(Vol. 17 Page 7175)

I re-establish sec.cor. by setting a basalt stone 14x6x6 ins. in the ground for corner, mkd. with 4 notches on S. and 3 notches on E. edges and raised a mound of stone 2 ft. base, 1½ ft. high, W. of corner. Pits impracticable. No sound trees within limits.

BLM resurvey by Lynn Roseberry & James Jelley, under Group #662 -Surveyed Oct. 1967/June 1969 (DCSO records, Vol. 38 Page 15539)

-----  
Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd:

T 30 S R 5 W  
S 9 | S 10  
S 16 | S 15  
1969

from which

- A Fir 10" dia., N.74¼°E., 24 lks. mkd. T30S R5W S10 BT.
- A Fir 28" dia., S.57½°E., 49 lks. mkd. T30S R5W S15 BT.
- A Fir 16" dia., S.13½°W., 44½ lks. mkd. T30S R5W S16 BT
- A Fir 22" dia., N.58°W., 13 lks. mkd. T30S R5W S9 BT.

Found a basalt stone, 14 x 6 x 6 ins., with chisel marks, lying loose on hillside and deposited it alongside iron post.

Fd. OK, by Wayne Rogers, Cadastral Surveyor, under Group #s 1000 and 1342 - Surveyed Aug. 1986 (DCSO records, Vol. 48 Page 18349)

Fd. OK, November 1986, H. Johnstone, M 103-1

continued next page

