

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 602100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2 only, T31-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 456 dated July 28, 1882 (DCSO rec. Vol. 17 Page 7163)

-----  
Set a Maple post 4 ft. long, 4" sq., 20" in the ground for the corner to secs. 1, 2, 35 and 36, mkd. T30S R5W S36 on the NE face, T31S S1 on the SE face, S2 on the SW faces, and S35 on the NW face, also one notch on the East and five notches on the W angles of the same, and from which

A Fir 14" dia., bears N.40°E., 26 lks. dist., marked  
T30S R5W S36 BT.

A Maple 12" dia., bears S.40°E., 29 lks. dist., marked  
T31S R5W S1 BT.

A Fir 24" dia., bears S.20°W., 56 lks. dist., marked  
T31S R5W S2 BT.

A Dogwood 6" dia., bears N.28°W., 15 lks. dist., marked  
T30S R5W S35 BT.

Victor S. King, L.S. #442 - For: Bate Lumber Co. - April 8, 1959 - C.S. File 42/425-8

-----  
Found - Clump of Dogwood N.28°W., 9.9 ft.  
Orig. BT, 16" Fir N.40°E., 17.2 ft. rescribed in bark S36 T30S R5W BT.  
Orig. BT, 40" Fir, bark scribed, S.20°W., 37.0 ft., rescribed in bark, S2 T31S R5W BT.

Set 3" square dogwood post.

New BTs -4" Dogwood N.19°W., 7.3 ft. scribed S35 T30S R5W BT.  
40" Fir bark scribed S1 T30S R5W BT.

Rescribed in bark, 2 original BTs as noted above.

Doug. County Surveyors Office - James Byron, Deputy - Mike Darby; Jim Halterman - 1963 - C.S. File 53/26-45

-----  
Found - 3" sq. stake at corner and BTs as recorded by King.  
Set Brass cap at cor. mkd: County Surveyors S35|S36 T30S  
Office, 1963 S 2|S 1 T31S R5W

No new bearing trees.

BLM resurvey by Jolley, Roseberry, and Brooks, under Group #'s 320 and 614 - Surveyed June 1966/May 1968 (DCSO records, Vol. 35 Pages 14356-57)

-----  
The Cor of secs. 1 and 2 only established by Byars in 1882, perpetuated and recorded by King in 1959, again perpetuated and recorded by Byron in 1963, monumented with an iron post, 1" dia., protruding 16" above ground, firmly set, with brass cap mkd. COUNTY SURVEYORS OFFICE T30S R5W S35 S36 S1 S2 T31S 1963, from which the remaining original bearing trees: Cont

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 602100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2 only, T31-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A Fir snag 19" dia., bears N.40°E., 26 lks. dist. with a healed blaze. Remarked RS 442 S36 T30S R5W BT on the bark by King in 1959.  
A Fir 45" dia., bears S.20°W., 52 lks. dist. with illegible scribe marks visible on bark blaze. Remarked S2 T31S R5W BT on the bark by King in 1959. (Rec. 56 lks.)  
A Dogwood clump bears N.28°W., 15 lks. dist. and bearing trees mkd. by King in 1959  
A Fir 38" dia., bears S.51°E., 55 lks. dist., with scribe marks RS 442 S1 T31S R5W BT visible on a bark blaze.  
A Dogwood 5" dia., bears N.15°W., 11 lks. dist., with scribe marks S35 T30S R5W BT visible on open blaze.  
At the corner point  
Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd:  
T 30 S R 5 W  
    S 36  
    S 2 | S 1  
T 31 S R 5 W  
    1967  
RESET the local iron post inverted alongside the iron post.

---

Corner Fd. OK, by Berry and Akin under Group #800, Surveyed Sept. 1972/June 1973 (DCSO records, Vol. 38 Page 15653)

---

DCSO-GIS Corner visitation - 7/19/2005 - Typed: 2/8/2011 - C.S. File 67/33-1

---

Monument - 2¼" IP/BC ----- Comment - (needs) rehab

---