

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 100400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19; 13 & 24, T30-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Volume 17 Page 7190)

Set post, cor. to secs. 18,19, 13 and 24, from which
A B.Oak 15" dia., bears S.50°E., 122 lks.
A B.Oak 24" dia., bears S.60°W., 327 lks.
A B.Oak 23" dia., bears N.70°E., 70 lks.
No other trees convenient NW.

Claude Kerr - June 1953 - C.S. File 41/160

I found two original B.Oak BTs which bears
S.60°W., 327 lks., which is now a 44" tree.
N.70°E., 70 lks. and is now a 38" B.Oak.
I set 3" x 3" x 4 ft. Cedar stake for the corner from the
original bearing trees, marking it S13, S24, S7, and S18.

Howard Johnstone, For: Roseburg Lumber Co. - Aug. 18, 1962
C.S. File 51/163-11

Found - 24" B.Oak S.60°W., 327 lks., now 36" and dying.
23" B.Oak N.70°E., 70 lks., now 32" and dying.
15" B.Oak S.50°E., 122 lks., good, now 24:.
Set 1" x 30" Iron pipe.
New BTs -16" Pine S.28°W., 58.0 ft.
12" Fir N.51½E., 50.0 ft.
22" Pine N.51°W., 3.6 ft.

BLM resurvey by Jelley and Akin, under Group #'s 734 and 829
Surveyed April 1971/Oct. 1973 (DCSO records, Vol. 37 page
15142)

The Sec. cor., perpetuated and recorded by Johnstone, 1962,
monumented with an I.P. 1" dia., firmly set, projecting 10"
above ground, from which the remains of the original bearing
trees:

A B.Oak snag 23" dia., bears N.70°E., 70 lks. dist., with
partially opened blaze.
A B.Oak 15" dia., bears S.50°E., 122 lks. dist., with
partially opened blaze.
A B.Oak 25" dia., bears S.60°W., 327 lks. dist., with
partially opened blaze.
and bearing trees mkd. by Johnstone
A root hole bears N.51½°E., 76 lks. dist., with a down
fir, alongside, 12" dia., with partially healed double
blaze. (Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 18 & 19; 13 & 24, T30-7

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

A Pine 20" dia., bears S.28°W., 88½ lks. dist., with partially healed double blaze.

A Pine 25" dia., bears N.51°W., 5½ lks. dist., with scribe marks T30S R7W S13 BT visible on partially healed double blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, directly over the iron pipe, with brass cap mkd:

T 30 S	
R 7 W	R 6 W
S 13	S 18
S 24	S 19
1973	

from which a new bearing tree

A Fir 15" dia., bears N.13½°E., 156 lks. dist., mkd. t30S R7W S18 BT.

Doug. County Surveyors Office - Randall Smith, Deputy - Stephen Flause; Hilary Simmons; John Pike - May 3, 1991 - C.S. File 64/15-1

Found - A 3¼" dia., 1973 BLM brass cap on a 2¼" O.D. I.P. protruding 12" above ground.

23" now 38" dia. 40 ft. high dead B.Oak snag with an opened blaze marks "S" visible bears N.76°E., 48.0 ft. (Rec. N.70°E., 46.2 ft.) (Orig. BT)

15" now 36" dia., 12" high B.Oak stump with possible lower blaze, bears S.47°E., 79.6 ft. (Rec.S.50°E., 80.5 ft. dist. is a slope measurement) Orig. BT.

24" now 48" dia. 4 ft. high B.Oak stump with a "V" open rotted blaze bears S.62°W., 215.8 ft. (Rec. S.60°W., 215.8 ft.) Orig. BT.

25" now 26" dia. P.Pine with partially healed double blaze illegible scribing visible, bears N.51°W., 3.6 ft. (agrees w/record)

20" now 19" dia. 17 ft. high P.Pine snag with partially healed double blaze, illegible scribe marks visible bears S.29½°W., 55.8 ft. (Rec. S.28°W., 58.0 ft. dist. is a slope measurement)

Johnstone's NE BT is gone.

New BTs -5" dia. D.Fir double blazed and scribed "T30S R7W S24 CS BT" bears S.45½°W., 11.7 ft.

5" dia. D.Fir double blazed and scribed "T30S R6W S18 CS BT" bears N.40°E., 9.0 ft.

5" dia. D.Fir double blazed and scribed "T30S R6W S19 CS BT" bears S.66½°E., 52.2 ft.

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 100400

PRIMARY CORNER DESCRIPTION Secs. Cor. for 18 & 19; 13 & 24, T30-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Mark Smalley - For: Roseburg Resources Co. - Feb. 1999 - M129-43

Found - 1973 BLM brass cap on IP
7" Fir S.66½°E., 52.2 ft., healed.
38" Oak N.76°E., 48.0 ft., snag OBT.
36" Oak S.47°E., 79.6 ft., stump OBT.
26" P.Pine N.51°W., 3.6 ft., low stump.
Scribed- 7" Fir S.5°W., 22.7 ft., "S 24 BT"
7" Fir N.39°E., 29.8 ft., "S 18 BT"
No other trees available.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2191, Surveyed April/May 2008 - (DCSO records Vol. 56 Page(s) 22129-30)

The cor. of secs. 13, 18, 19, and 24, on the E. bdy. of the Tp., perpetuated by Smith, in 1991, subsequently perpetuated by Smalley, in 1999, bears S.0°21'23"W., 2618.73 ft., monumented with an iron post, 2½" dia., firmly set, projecting 11" above ground, with brass cap (properly) mkd. from which the remains of the original bearing trees

A roothole, bears N.76°E., 48.2 ft., alongside of which is a down, decayed oak snag, 40" dia., with no marks visible on a hollow, open blaze. (Record, N.70°E., 46.2 ft.)

A sawed, decayed oak stump, 36" dia., bears S.47°E., 80.5 ft., with no marks visible. (Record, S.50°E.)

A sawed, decayed oak stump, 44" dia., bears S.61½°W., 215.8 ft., with no marks visible. (Record, S.60°W.)

and the remains of BTs mkd. by Johnstone, in 1962, reported by Jelley and Akin

A roothole, bears N.51½°E., 50.2 ft., alongside of which is a down, decayed fir snag, 12" dia., with no marks visible.

A sawed, pine stump, 28" dia., bears N.51°W., 3.6 ft., with fragmentary scribe marks visible on a partially healed blaze and a metal cap.

and the remains of the bearing tree mkd. by Jelley and Akin

A roothole, bears N.13½°E., 103.0 ft., alongside of which is a down, decayed fir snag, size indeterminate, with no marks visible on an opened blaze.

and a bearing tree mkd. by Smith

A fir, 10" dia., bears S.66¾°E., 52.5 ft., with a healed double blaze.

and bearing trees mkd. by Smalley

continued next page

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 100400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19; 13 & 24, T30-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 8" dia., bears N.37°E., 29.2 ft., with a healed blaze.
A fir, 10" dia., bears S.5½°W., 22.3 ft., with a healed blaze.
and a new bearing tree
A fir, 7" dia., bears N.41¼°W., 36.2 ft., mkd. T30S R7W S13 BT.
Corner is located on a SW. slope, 35 ft. W. of a spur, slopes South.

Brent Knapp - For: Roseburg Resources Co. - 8/2023 - M182-53

Found - 1973 BLM brass cap
Roothole; N.76°E., 48.2'
Rotten Oak stump; S.47°E., 80.5'
44" sawed & decayed Oak stump, no markings visible;
S.61½°W., 215.8'
Roothole; N.51½°E., 50.2'
28" sawed Pine stump, partially open scar fragmented
scribing, metal cap on tree, tags, N.51°W., 3.6'
11" Fir, healed scar & tag; S.67°E., 52.5'
8" Fir, healed scar & tag; N.37°E., 29.2'
12" Fir, healed scar & tag; S.5°W., 22.3'
10" Fir, healed scar & tag; N.42°W., 36.2'