

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 140500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 7 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Vol. 17 Page(s) 7224)

Set quarter sec. post, from which a
Laurel 8" dia., bears S.25°E., 120 lks. dist.
Red Fir 16" dia., bears N.15°W., 17 lks. dist.

BLM resurvey by Jelley & White under Group #s 350 & 551, Survey May 1963/July 1964 (DCSO records, Vol.32 Pgs 13585-86)

The ¼ sec. cor. of secs.7 and 18, determined at record bearing and distance from the remaining original bearing tree:

A Fir 42" dia., bears N.15°W., 17 lks. dist. with scribe marks S and other illegible marks visible on opened blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd: T 30 S R 6 W

¼ $\frac{S 7}{S 18}$

from which a new bearing tree

A Fir 23" dia., bears S.56°E., 58 lks. dist.,
mkd. ¼ S18 BT.

Douglas Co. Surveyors Office - Vernon Ray Tracy; Frank Jones March 18, 1969 - C.S. File 53/40-113

Found - 1964 Cadastral brass cap at corner, firmly set and properly marked.

Orig. 42" D.Fir N.15°W., 11.2 ft. alive in good condition, "¼ S4" scribe.

1964 Cadastral BT, face down.

New BT -14" D.Fir S.38°W., 51.8 ft. mkd: ¼ S18 CS BT.

This corner lies on steep NW slope approx. 125 ft. south of creek, course westerly, in old growth timber.

See BLM for a 1977 Administrative survey