

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 6 and 7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Under Contract #56, dated March 1855 (DCSO records Vol. 17 Page(s) 7226)

Set quarter sec. post, from which a
W.Oak 28" dia., bears N.64°W., 435 lks. dist.
W.Oak 22" dia., bears S.85°W., 427 lks. dist.

BLM resurvey by Jelley & White under Group #s 350 & 551, Survey May 1963/July 1964 (DCSO records, Vol. 32 Pg. 13588)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd: T 30 S R 6 W

¼ $\frac{S\ 6}{S\ 7}$

from which

A Fir 16" dia., bears N.11½°W., 118 lks. dist., mkd.
¼ S6 BT.

A W.Fir 10" dia., bears S.3°E., 115 lks. dist.,
mkd. ¼ S7 BT.

Corner is located at the cor. of timber, logged to the north and west.

From this point, a stone 18 x 18 x 10" above ground, firmly set, bears S.79°00'W., 1.82 chs. dist., established by persons unknown, from which local bearing trees:

A Fir 15" dia., bears N.74°E., 18 lks. dist., with mark s and other illegible marks visible on partially healed blaze, appears to have been marked with a knife about 20 years ago.

A sawed Fir stump 35" dia., bears S.20°E., 37 lks. dist., with healed blaze.